

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐
well well other

2. NAME OF OPERATOR
TEXACO Inc.

3. ADDRESS OF OPERATOR
P.O. Box 728 Hobbs, NM 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 2970' FNL & 2310' FEL of Sec
AT SURFACE: 27, T-26-S, R-37-E, Unit
AT TOP PROD. INTERVAL: Letter 'J', Lea County
AT TOTAL DEPTH: New Mexico

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF	<input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>	<input type="checkbox"/>
(other)		

5. LEASE
LC-030174 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
W.H. Rhodes B Fed NCT-1

9. WELL NO.
2

10. FIELD OR WILDCAT NAME
Rhodes Yates

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec 27, T-26-S, R-37-E

12. COUNTY OR PARISH 13. STATE
Lea NM

14. API NO.
Regular

15. ELEVATIONS (SHOW DF, KDB, AND WD)
2988' (GR)

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

RECEIVED
JUL 3 1978
U.S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Rigged up. Install BOP. Pulled pumps and rods.
2. Clean out to 3275'.
3. Set pkr @ 3016'. Acidize open-hole 3077'-3275' w/3000 gal HCL NE Acid using 1000# brine water and 400# rock salt. Flush w/ 35 bbl treated water.
4. Install pumping equipment. On 24 hr potential test ending 6-28-78, well pumped 3 BO, 18 BW, GOR 800.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED _____ TITLE Asst. Dist. Supdt DATE 6-30-78

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

