

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-163
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-12072
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEB <input type="checkbox"/>
6. State Oil & Gas Lease No. B-8580
7. Lease Name or Unit Agreement Name RHODES YATES UNIT
8. Well No. 5
9. Pool name or Wildcat RHODES YATES SEVEN RIVERS
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 2979' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER INJECTION WELL <input type="checkbox"/>
2. Name of Operator Texaco Exploration and Production Inc.
3. Address of Operator P. O. Box 730 Hobbs, NM 88240
4. Well Location Unit Letter <u>D</u> : <u>660</u> Feet From The <u>NORTH</u> Line and <u>660</u> Feet From The <u>WEST</u> Line Section <u>27</u> Township <u>26-S</u> Range <u>37-E</u> NMPM LEA
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 2979' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU. RELEASE PKR. CLEAN OUT TO 3200'.
2. FREEPT 4 1/2" LINER. CUT & PULL LINER @ 3190. CLEAN OUT TO 3329'.
3. PERFORATE FROM 3125'-3140'.
4. FRACTURE PERF'S W/14,500 GALS GEL AND 74,000# SAND.
5. TIH W/ 2 3/8" TBG AND PKR. SET PKR @ 3075'. LOAD BACKSIDE W/PKR FLUID. PRESSURE TEST (NOTIFY OCD FOR WITNESS). PUT ON INJECTION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Dal de Aragao TITLE Production Engineer DATE 01-04-94

TYPE OR PRINT NAME Darlene D. de Aragao TELEPHONE NO. 393-7191

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE JAN 10 1994

CONDITIONS OF APPROVAL, IF ANY: