

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on
verse side)

Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	5. LEASE DESIGNATION AND SERIAL NO. LC-030168B
2. NAME OF OPERATOR Conoco Inc.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, New Mexico 88240	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FNL & 1980' FWL - Unit Letter F	8. FARM OR LEASE NAME Eaves B-1
	9. WELL NO. 3
	10. FIELD AND POOL, OR WILDCAT Scrubrough Uates 7 Res
	11. SEC., T., E., M. OR BDM. AND SURVEY OR AREA 30-26S-37E
14. PERMIT NO. 30-025-12080	12. COUNTY OR PARISH Lea
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETION

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

MIRU. Run csq scraper to 2960'. POOH. Set CIBP at 2950'. Mix mud & circ hole clean. Pressure test csq to 500 psi for 15 mins, held okay. Spot 23 sxs class "C" cement at 2950'. Pull 25 stds & WOC. GIH & tag plug at 2658'. Pull up to 1500' & spot 23 sxs cement. POOH. Ref w/ 4 spf at 410'. Bullhead squeeze 165 sxs cement & circulate. Install P&A marker on 4/26/88.

RECEIVED
JUN 28 11 00 AM '88
OFFICE OF THE
ADMINISTRATIVE SUPERVISOR

18. I hereby certify that the foregoing is true and correct

SIGNED *[Signature]* DE FINNEY

TITLE Administrative Supervisor

DATE June 27, 1988

FOR SPACE FOR (Federal or State office use)

APPROVED *[Signature]* MURDOCK

TITLE

DATE 7-19-88

COMMENTS OF APPROVAL, IF ANY:

Approved for use in the well bore.
This report is to be used only
for the purpose for which it was prepared.

*See instructions on Reverse Side

This form is a government document. It is a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM - Caswell (6) ARCO (2) Amoco (2) Chevron (1) File

E