

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND AND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR CONOCO INC.	8. FARM OR LEASE NAME Eaves A
3. ADDRESS OF OPERATOR P. O. Box 460, Hobbs, N.M. 88240	9. WELL NO. 13
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit B 660' FNL & 1980' FEL	10. FIELD AND POOL, OR WILDCAT Scarborough-Yates 7 Rurs
14. PERMIT NO. 30-025-12081	11. SEC., T., R., E., M., OR BLK. AND SURVEY OR AREA Sec. 30 - 26S - 37E
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETION ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	
(Other) open add'l pay & acidize ☒		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- ① MIRU, POOH w/ rods & pump. G/H w/ bit & scraper to 3100'
- ② G/H w/ GR/CCL/CBL tool and E/L. Log from 3100'-2700'. Correlate w/ existing neutron log
- ③ Set RBP @ 3000' and test to 1000 psi. Spot 2 bbls 15% HCL-NE-FE acid from 2975'-2893'.
- ④ Perf w/ 2 JSPF @ 2949', 52', 55', 57', 59', 61', 63', 66', 70' (total 18 holes)
- ⑤ Set pkr @ 2920'. Acidize w/ 36 bbls 15% HCL-NE-FE acid, flush w/ 13 bbls 9.0 Hg brine. Swab.
- ⑥ Test pump 4-6 perfs. If perfs don't produce commercial production, a squeeze procedure will follow.
- ⑦ Verbal approval of this procedure per Bob Pitscke on 2/18/86.

18. I hereby certify that the foregoing is true and correct

SIGNED <u>[Signature]</u>	TITLE <u>Administrative Supervisor</u>	DATE <u>2-18-86</u>
(This space for Federal or State office use)		
APPROVED BY <u>[Signature]</u>	TITLE <u>ACTIVE</u>	DATE <u>2-28-86</u>
CONDITIONS OF APPROVAL, IF ANY:		

*See Instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carlsbad (6) ARCO (2) Amoco (2) Chevron (1) File

RECEIVED
MAR 3 - 1986
C.C.D.
HOBBS OFFICE