	PARTME IT	
AT ION		
U.S.G.S.		

OIL CONSERVATION DIVISION

P. O. BOX 2088 SANTA FE, NEW MEXICO 87501	Form C-103 Revised 10-1-7- Sa. Indicate Type of Lease
U.S.G.S. LAND OFFICE OPERATOR	State X Fee 5. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. (DO NOT USE THIS FORM FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name State "0"
Bert Fields, Jr. J. Address of Operator 5535 Yale Blvd. Suite 200 Dallas, TX 75206	9. Well No. 10. Field and Pool, or Wildcat
UNIT LETTER E , 330 FEET FROM THE West LINE AND 2310 FEET FROM	JalMat T-Y-SR
THE North LINE, SECTION 32 TOWNSHIP 26S RANGE 37E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.)	12. County Lea
Check Appropriate Box To Indicate Nature of Notice, Report or Oth NOTICE OF INTENTION TO: SUBSEQUENT	er Data REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB OTHER	ALTERING CASING PLUG AND ABANDONMENT
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposea
1. Spot 40 sxs @2880' - tag 2640' 2. Spot 40 sxs @1250' - 1050' 3. Spot 40 sxs @200' - surface	
Install dry dole makrer Well circulated with 10# mud	
and helpf	
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Richard Mayo Marrs Casing Pulling. TITLE Inc.	DATE
Jack Griffin DIE & GAS INSPECTOR	JAN 2 1 1988