

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

O+2-NMOCD-P.O. Box 1980 1-Foreman-CRM

Hobbs, NM 88240 1-File

1-Engr. JIM

1-Engr. Tech

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-1732	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name West Dollarhide	
2. Name of Operator Getty Oil Company		8. Farm or Lease Name Drinkard Unit	
3. Address of Operator P.O. Box 730 Hobbs, NM 88240		9. Well No. 74	
4. Location of Well UNIT LETTER C 667 FEET FROM THE North LINE AND 631 FEET FROM THE East LINE, SECTION 4 TOWNSHIP 25S RANGE 38E NMPM.		10. Field and Pool, or Wildcat Dollarhide Tubb-Drinkard	
15. Elevation (Show whether DF, RT, GR, etc.) 3171' KB		12. County Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

2/13/82 Rigged up Gene's Well Service
2/15/82 Pulled rods pump & tubing.
2/16/82 Ran tubing. Tagged fill @ 6462'. TOH.
2/17/82 Rigged up Homco.
2/18/82 Drilled out fill 6462-6557'; Tagged bottom 6846'. Circulated clean.
2/19/82 Dresser Titan acidized with Baker pkr. @ 6374' w/2000 gals. 15% NE HCL & squeezed w/3 drums scale inhibitor.
2/20/82 Ran tubing and rods. Placed well back on production.
2/22/82 Rigged down unit.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Donald J. Steinnard TITLE Area Superintendent DATE March 24, 1982

ORIGINAL SIGNED BY

MAR 31 1982

APPROVED BY JERRY DEXTON

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAR 30 1982

O.C.D.
HOBBS OFFICE