

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>

5. State Oil & Gas Lease No.

**B-1732**

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER - <b>Water Injection</b>	7. Unit Agreement Name <b>West Dollarhide Queen Sand Unit</b>
2. Name of Operator <b>Skelly Oil Company</b>	8. Farm or Lease Name <b>West Dollarhide Queen Sand Unit</b>
3. Address of Operator <b>P. O. Box 1351, Midland, Texas 79701</b>	9. Well No. <b>54</b>
4. Location of Well UNIT LETTER <b>D</b> , <b>330</b> FEET FROM THE <b>North</b> LINE AND <b>330</b> FEET FROM THE <b>West</b> LINE, SECTION <b>4</b> TOWNSHIP <b>25S</b> RANGE <b>38E</b> NMPM.	10. Field and Pool, or Wildcat <b>Dollarhide Queen</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3154' GR</b>	12. County <b>Lea</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Rigged up pulling unit 12-8-72. Pulled tubing and packer.
- 2) Set 7" bridge plug at 3540'.
- 3) Circulated hole with 10.2# mud.
- 4) Spotted 15 sacks of cement 3465-3540'.
- 5) Spotted 100 sacks of cement 1065-1547'.
- 6) Spotted 10 sacks of cement in top of 7" casing and cellar.
- 7) Set marker.

All intervals not cemented were filled with 10.2# mud. No casing was pulled. 9-5/8" OD 36# casing set at 350' and 7" OD 20# casing set 3600' were left in the hole. Well plugged and abandoned 12-9-72.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

(Signed) D. R. Crow

SIGNED D. R. Crow TITLE Lead Clerk DATE Jan. 25, 1973

APPROVED BY John W. Ramsey TITLE Lead Clerk DATE Jan. 25, 1973

CONDITIONS OF APPROVAL, IF ANY: