

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 12-1-

3a. Indicate Type of Lease
State ☒ Fee ☐

3. Since Oil, 4. Gas Lease No.
LC 062368

SUNDY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OFFER TO PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" FORM C-101 FOR SUCH PROPOSALS.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER *WI*

2. Name of Operator
Chevron U.S.A. Inc.

3. Address of Operator
P. O. Box 670, Hobbs, NM 88240

4. Location of Well
UNIT LETTER *L* *1980* FEET FROM THE *South* LINE AND *660* FEET FROM
THE *West* LINE, SECTION *4* TOWNSHIP *25S* RANGE *38E* NMPM.

5. Unit Agreement Name
Devonian Unit

6. Name of Lease Name

9. Well No.
117

10. Field and Pool, or Wildcat
Devonian N. Dollarkide

15. Elevation (Show whether DF, RT, CR, etc.)

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐

CHANGE PLANS ☐

OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

COMMENCE DRILLING OPS. ☐

CASING TEST AND CEMENT JOBS ☐

OTHER *TA*

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

*Pot hole pkv + thg. Set CIBP @ 8220', test 500#-ok. Dump
5-4 Cmt on CIBP. Circ hole up pkv fluid. TA 8-25-85*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *RJ Sexton*

TITLE *DIV. PETR. ENGINEER*

DATE *8-27-85*

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

SEP - 3 1985

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

AUG 30 1985

**O.C.D.
HOBBS OFFICE**