

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division

P.O. Box 19
Hobbs, NM 88241

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator
OXY USA Inc.

16696

3. Address and Telephone No.
P.O. Box 50250 Midland, TX 79710-0250

915-685-5717

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

2310 FSL 990 FWL NWSW(4) Sec 5 T25S R38E

5. Lease Designation and Serial No.

8910084910 - NMLC067164

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

W. Dollarhide Qn Sd Unit
008596

8. Well Name and No.

61

9. API Well No.

30-025-12364

10. Field and Pool, or Exploratory Area

Dollarhide Queen

11. County or Parish, State

Lea NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

TD - 3745'

NOTIFY BLM OF P&A. MIRU PU 3/17/96, ND WH, NU BOP. RIH & TAG CIBP @ 3325', POOH TO 3300', SPOT 20sx CL C CMT, M&P 9.5# MUD-LADEN BW, POOH TO 2600'. SPOT 25sx CL C CMT PLUG @ 2600-2500', PU TO 2500', M&P 9.5# MUD-LADEN BW. RIH & PERF 4 SQZ HOLES @ 1300', RIH & SET CR @ 1200', UNABLE TO EIR, POOH W/ CR & SPOT 35sx CL C CMT PLUG @ 1300-1100', M&P 9.5# MUD-LADEN BW, POOH. RIH & TAG CMT @ 1100'. RIH & PERF 4 SQZ HOLES @ 300', RIH & SET CR @ 200', M&P 45sx CL C CMT PLUG, LEAVE 5sx CMT ON CR. POOH TO 50', SPOT 10sx CL C CMT PLUG TO SURF. NDBOP, RDPU-3/19/96, CUTOFF WH, CLEAN LOCATION & BACKFILL ALL PITS, INSTALL DH MARKER. ANDY CORTEZ W/ BLM WITNESSED PLUGGING PROCEDURES.

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

14. I hereby certify that the foregoing is true and correct

Signed

David Stewart

Title

David Stewart
Regulatory Analyst

Date

3/7/97

(This space for Federal or State office use)

(ORIG. SGD.) DAVID R. GLASS

Title

PETROLEUM ENGINEER

Date

MAR 13 1997

Approved by
Conditions of approval, if any:

