

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

3002512387

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil / Gas Lease No.

B-9312-5

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.

7. Lease Name or Unit Agreement Name

WEST DOLLARHIDE DRINKARD UNIT

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

8. Well No.
88

3. Address of Operator
205 E. Bender, HOBBS, NM 88240

9. Pool Name or Wildcat
DOLLARHIDE TUBB DRINKARD

4. Well Location
Unit Letter A : 667 Feet From The NORTH Line and 500 Feet From The EAST Line
Section 5 Township 25S Range 38E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☒ Convert injector to pumping

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-08-00: RU REV UNIT. SET TWO ANCHORS & TEST ALL. PUMP 20 BBLS DN TBG. NDWH. NUBOP. UNSET PKR.
2-09-00: FLOWED TO FRAC TANK. TIH W/BIT, CSG SCRAPER. STOP BIT @ 4652'.
2-10-00: TAG FILL @ 6370'. TIH W/BIT ON WS. BREAK CIRC & C/O SCALE & IRON SULFIDE 6370-6510'.
2-11-00: TIH W/PKR, & SN ON TBG. SET PKR @ 6306'. LOAD & TEST BACKSIDE TO 500#-OK.
2-14-00: ACIDIZE DRINKARD PERFS 6397-6502' W/4000 GALS 15% NEFE HCL.
2-15-00: RU SWAB. FL @ SURF. END FL @ 3000'. SCALE SQZ DRINKARD PERFS 6397-6502 W/165 GALS TH-756 MIXED IN 30 BBLS 2% KCL.
FLSH W/5 GALS ALPHA 133.
2-16-00: UNSET PKR. LOWER PKR & TAG PBTD @ 6510'. NO FILL. TIH W/OPSMA, SN, TBG, TAC. TBG @ 6477'. SN @ 6459'. TAC @ 6357'.
2-17-00: NDBOP. NUWH.
2-18-00: TIH W/GAS ANCHOR, PUMP, SNKR BARS, RDS. LOAD & TEST WELL TO 500#-OK.
2-21-00: RIG DOWN.
2-27-00: ON 24 HR OPT. PUMPING 69 BO, 137 BW, & 4 MCF. PERFS 6397-6502'.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 3/7/00

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY: TITLE

DATE MAR 21 2000