

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

JUL 22 2 13 PM '69

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
NM 0569	
7. Unit Agreement Name	
8. Farm or Lease Name	
El Paso Ginsberg	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
1	
11. County	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> <b>Dry</b>
2. Name of Operator <b>J. Lohmann Oilwell Service, Inc.</b>
3. Address of Operator <b>8 Miles Northeast of Jal</b>
4. Location of Well UNIT LETTER _____, <b>1980</b> FEET FROM THE <b>North</b> LINE AND <b>560</b> FEET FROM THE <b>West</b> LINE, SECTION <b>7</b> TOWNSHIP <b>25S</b> RANGE <b>38E</b> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATIONS <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
		OTHER <b>Reentry</b>	<input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Subject well re-entered 7-14-69 to test Penn Detrital. Cleaned out to 8606 Logged.  
To be plugged and abandoned with 25 sx @ 8500', 25 sx @ 6950', 25 sx @ 5150',  
25 sx @ 4100', 25 sx. @ 2650', 10 sx @ surface.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>J. Lohmann</i></u>	TITLE <b>President</b>	DATE <b>July 18, 1969</b>
APPROVED BY <u><i>[Signature]</i></u>	TITLE <u>                    </u>	DATE <u>                    </u>
CONDITIONS OF APPROVAL, IF ANY:		