

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

1a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" FORM C-101 FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. Unit Agreement Name	
2. Name of Operator V. H. Westbrook		8. Farm or Lease Name Buffington 'C'	
3. Address of Operator P.O. Box 2264 Hobbs, New Mexico 88240		9. Well No. 1	
4. Location of Well UNIT LETTER <u>M</u> <u>330</u> FEET FROM THE <u>West</u> LINE AND <u>430</u> FEET FROM THE <u>South</u> LINE, SECTION <u>18</u> TOWNSHIP <u>25S</u> RANGE <u>38E</u> N.M.P.M.		10. Field and Pool, or Wildcat Justis Paddock	
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Lea	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING CPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Plug back from Blinbry to Paddock Formation

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

June 24, 1974:
Pulled & layed down rod string.

June 25, 1974"
Pulled tubing, set 5½" CIBP at 5100' w/35' cement.
Ran tubing with Baker Model E Packer to 4800'.

June 26, 1974:
Perforated 4976,4977, 4978, 79, 80, 96, 97, 98 w/tubing gun.

June 27, 1974:
Acidized perms with 1000 gals., 15% HCL acid and displaced. Swabbed well down to seating nipple.

June 28, 1974:
Ran swab to seating nipple. No fluid or gas, preparing to plug & abandon.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Secretary DATE 7-5-74

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: