

NEW MEXICO OIL CONSERVATION COMMISSION
Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON RESULT OF TEST OF CASING SHUT-OFF	<input checked="" type="checkbox"/>	REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL		REPORT ON RECOMPLETION OPERATION		REPORT ON (Other)	

May 31, 1955

(Date)

Hobbs, N. M.

(Place)

Following is a report on the work done and the results obtained under the heading noted above at the

W. K. Byrom

(Company or Operator)

Buffington

(Lease)

Velma Petroleum Corporation

(Contractor)

Well No. 2 in the SW 1/4 SW 1/4 of Sec. 19

T. 25S, R. 38E, NMPM., Undesignated Pool, Lea County.

May 25, 1955

The Dates of this work were as follows:

Notice of intention to do the work (was) (was not) submitted on Form C-102 on _____, 19____.

(Cross out incorrect words)

and approval of the proposed plan (was) (was not) obtained.

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Ran 5-1/2" 14# casing, set at 3270', cemented with 300 sacks cement.
200 sacks on bottom and 100 sacks on top of Rustler. Set 48 hours.
Tested with 1000# cold water for 30 minutes. No drop in pressure.

Witnessed by Sid James Velma Petroleum Corp. Drilling Supt.

(Name)

(Company)

(Title)

Approved: OIL CONSERVATION COMMISSION

(Name)

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name

Position Agent

Representing W. K. Byrom

Address 1000 N. Dal Paso, Hobbs, N. M.

(Title)

(Date)