

Submit 3 Copies To Appropriate District
 Office
 District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 1301 W. Grand Avenue, Artesia, NM 88210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised March 25, 1999

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 30-025-12421	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name: L.M. Buffington B	
8. Well No. 2	
9. Pool name or Wildcat Justis, Tubb, Drinkard	

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. **Type of Well:**
 Oil Well Gas Well Other

2. **Name of Operator** Chevron USA, Inc.

3. **Address of Operator** 15 Smith Rd. Midland, Tx 79705

4. **Well Location**
 Unit Letter L : 1650 feet from the south line and 330 feet from the west line
 Section 19 Township 25-S Range 38-E NMPM County Lea

10. **Elevation** (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. **Describe proposed or completed operations.** (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. Tag 7" CIBP @ 5760 spot 40sx plug fr/5760-5660 Tag @ 5550
2. Spot 40sx plug fr/4800-4600(Glorieta)
3. Spot 40sx plug fr/3700-3500(Queen) Tag @ 3489
4. Perf 4 holes @ 3375 unable to sqz spot 60sx plug fr/3375-3250(9 5/8 shoe)Tag @ 3162
5. Perf 4 holes @ 2400 unable to sqz spot 60sx plug fr/2400-2200(B-salt)Tag 2182
6. Perf 4 holes @ 1100 unable to sqz spot 60sx plug fr/1100-900(T-salt) Tag @ 856
7. Perf 4 holes @ 600 & 400 unable to sqz circ cmt fr/650 to surf w/120sx (13 3/8 shoe)Tag @ surf
8. Install dry hole marker 12-21-02

Approved as to Plugging of the Well Bore.
 Liability under bond is retained until
 Surface restoration is completed.

JAN 2003

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE MANAGER/SUNSET DATE 12-21-02

Type or print name JIMMY BAGLEY Telephone No 915 520-8756
 (This space for State use)

APPROVED BY _____ TITLE _____ DATE JAN 09 2003
 Conditions of approval, if any: