DISTRIBUTION SANTA FE FILE D.S.G.S. LAND OFFICE OPERATOR SUNDRY	NEW MEXICO OIL CONSERVATION COMM SSION S. OFFICE				Form C-103 Supersedes Old C-102 and C-103 Effective 1-1-65 Sa. Indicate Type of Lease State Fee 5. State Cil & Gas Lease No. B-9521	
	N FOR PERMIT - 1 (FORM C	FEN OR PLUG BACK -101) FOR SUCH P	TO A DIFFERENT ROPOSALS.	RESERVOIR.		
OIL GAS WELL OTHER-					7. Unit Agreement Name	
Skelly 0il Company 3. Address of Operator P. O. Box 1351, Midland, 4. Location of Well	Texas 79701				8. Farm or Leas Hobbs "A" 9. Well No.	se Name
					10 Pi-14 = 1 P 1	
UNIT LETTER F . 1980 FEET FROM THE NORTH LINE AND 1650 FEET FR					Langlie Mattix	
THE West LINE, SECTION				8E NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)					12. County	. ////////////////////////////////////
Check At	opropriate Box To J		79' DF		Lea	
other 17. Describe irroposed or Completed Oper work) SEE RULE 1103. 1) Move in pulling unit. 2) Set 5-1/2" bridge plug 3) Circulate hole with 10 4) Spot 35' cement plug 5) Shoot off and salvage 6) Spot 100' cement plug 7) Spot 100' cement plug 8) Spot 10 sack cement plug 9) Set dry hole marker.	Pull rods and g at 3300'. 0.2# mud. on top of bridge approximately : across top of : across 8-5/8"	pertinent details, tubing. e plug at 3 2800' of 5-5-1/2" OD 6	and give pertino	ent dates, including e		starting any proposed
	ove is true and complete t	to the best of my	knowledge and I	polis		