

PLUGS AND ADAPTERS

Heaving plug—Material None Length None Depth set None
 Adapters—Material None Size None

SHOOTING RECORD

Shot	Shell used	Explosive used	Quantity	Date	Depth shot	Depth cleaned out
0	0	0				

TOOLS USED

Rotary tools were used from 0 feet to 0 feet, and from 0 feet to 0 feet
 Cable tools were used from 0 feet to 3976 feet, and from 0 feet to 0 feet

DATES

19 Put to producing 19

The production for the first 24 hours was None barrels of fluid of which 0 % was oil; 0 % emulsion; 0 % water; and 0 % sediment. Gravity, °Bé. 0

If gas well, cu. ft. per 24 hours 0 Gallons gasoline per 1,000 cu. ft. of gas 0

Rock pressure, lbs. per sq. in. 0

EMPLOYEES

J. H. Pope, Driller J. L. Baimbridge, Driller
N. W. Sanders, Driller 0, Driller

FORMATION RECORD

FROM—	TO—	TOTAL FEET	FORMATION
0	20	20	Sand
20	30	10	Caliche
30	105	75	Sand
105	350	245	Red Rock
350	380	30	Sand
380	975	595	Red Rock
975	1087	112	Anhy.
1087	1125	38	Sand
1125	1310	185	Red Rock
1310	1450	140	Anhy.
1450	1915	465	Salt
1915	2605	690	Salt & Anhy.
2605	2835	230	Brown Lime
2835	2970	135	Sand & shale
2970	3579	609	Grey Lime
3579	3600	21	Sand & Shale
3600	3640	40	Sand
3640	3670	30	Lime
3670	3685	15	Sand
3685	3850	165	Lime
3850	3870	20	Lime & sand
3870	3976	106	Lime - TD
FROM—	TO—	TOTAL FEET	FORMATION

(OVER)

FORMATION RECORD—Continued

16-43004-1