

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instruction on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NA-021422

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

-

7. UNIT AGREEMENT NAME

Antelope Ridge Unit

8. FARM OR LEASE NAME

Antelope Ridge Unit

9. WELL NO.

4-2

10. FIELD AND POOL, OR WILDCAT

Antelope Ridge

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

4-24-34

NRPM Survey

12. COUNTY OR PARISH

Lea

13. STATE

N. Mex.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	7. UNIT AGREEMENT NAME Antelope Ridge Unit
2. NAME OF OPERATOR Shell Oil Company	8. FARM OR LEASE NAME Antelope Ridge Unit
3. ADDRESS OF OPERATOR Box 1858 Roswell, New Mexico	9. WELL NO. 4-2
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990' FRA & 1010' FRA (10/4 10/4) Section 4, T-24, R-4, Lea County, New Mexico Unit 11-08-001-3492	10. FIELD AND POOL, OR WILDCAT Antelope Ridge
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 4-24-34 NRPM Survey
15. ELEVATIONS (Show whether DE, RT, GR, etc.) 3562' of	12. COUNTY OR PARISH Lea
	13. STATE N. Mex.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☐	

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Run 5155' of 8-5/8" (32#, J-55) casing and cemented at 5157' with 400 SX
Lone Star Class C plus 2% CaCl₂. Plug down - 11:46 a.m. (M.T), December
17, 1964. After 16 hours, tested with 600 psi for 30 minutes - no
pressure drop.

18. I hereby certify that the foregoing is true and correct

Original Signed By

SIGNED R. J. Doubek

TITLE Division Mechanical Engineer DATE Dec. 18, 1964

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____ DATE _____

APPROVED

DEC 21 1964

*See Instructions on Reverse Side

J. L. GORDON
ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.