

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-21229
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	23267

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> Convert to WIW	7. Lease Name or Unit Agreement Name Langlie Lynn Queen Unit
2. Name of Operator Energen Resources Corporation	8. Well No. 16
3. Address of Operator 3300 N. A St, Bldg 4, Ste 100, Midland, TX 79705	9. Pool name or Wildcat Langlie Mattix 7 RVRs/Queen/GB
4. Well Location Unit Letter <u>F</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>26</u> Township <u>23S</u> Range <u>36E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <u>Convert to WIW</u> <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU WSU, pull all production equipment. TIH w/ RBP to 3,500', pressure test casing to 500 psi for 30 minutes. POH & re-perforate the 7 RVRs/Queen @3,468'-72', @ 3,478'-86', and @ 3,502'-08'. Acidize w/ 3,000 gals. Run injection packer and tubing, perform casing integrity test and begin water injection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE D. Menoud TITLE Prod. Tech. DATE 3/13/2000
TYPE OR PRINT NAME Denise Menoud TELEPHONE NO. 915-687-2000

(This space for State Use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

OC FIELD REPRESENTATIVE/STAFF MANAGER
DATE