	DEPAR	TNNT OF THE INTE	ERIOR verse side)	e- Form appro Budget Bur	eau No. 4
		GEOLOGICAL SURVEY	at FE ALF ACTOC BING)	5. LEASE DESIGNATION NM-040763 Ur	
	SUNDRY NO	03 01		6. IF INDIAN, ALLOTT	
(Do not	use this form for prop	TICES AND REPORTS			
1.	Use "	CATION FOS PREMITE for suc	ug back to a different reservoir. ch proposals.)	_	
	GAS WELL X OTHER			7. UNIT AGREEMENT N	AME
WELL L					
Humble	Oil & Refinin	g Company	拉方合理方	S. FARM OR LEASE NA	
3. ADDRESS OF	PERATOR			Federal Dav	150n
Box 210	O, Hobbs, New	Mexico 88240			
	WELL (Report location e 17 below.)	clearly and in accordance with a	any State requirements.*	10. FIELD AND POOL,	OR WILDCA
At surface				Wildcat	
Lea Cour	nty, New Mexid	of NE/4 of Sec. 20,	T-24-S, R-36-E,	11. SEC., T., B., M., OR SURVEY OR ARE	BLE. AND
	New Mexic				· · · ·
14. PERMIT NO.		15. ELEVATIONS (Show whether	r DF, RT, GR, etc.)	Sec. 20, T-24 12. COUNTY OF PARISI	-S, R-
	-	3381 DF	·	Lea	New M
16.	Check A		Nature of Martin D		INGM IN
	NOTICE OF INTE		Nature of Notice, Report, or		
TEST WATER	LJ	· · · · · · · · · · · · · · · · · · ·	SUBSEC	QUENT REPORT OF :	-
TEST WATER FRACTURE TR		PULL OR ALTER CASING	WATER SHUT-OFF	BEPAIRING	·
SHOOT OB AC	1	ABANDON*	FRACTURE TREATMENT	ALTERING C	· · · · ·
REPAIR WELL		CHANGE PLANS	SHOOTING OR ACIDIZING	ABANDONME	NT*
(Other)	L		(Other) (NOTE: Report result	s of multiple completion pletion Report and Log fo	on Well
Ran 4550 Top of 1 4% Gel, 7-5/8" 1	(117 joints iner set insi salt saturate iner from 14.	s) 7-5/8" liner, P-1 de 10-3/4" casing a ed and 1# Mud Kill p 578' to 10.028'. W	10 & N-80, 39# & 33.70 t 10,028. Cemented wi er sx. POB 12:15 PM o OC 48 hours. Tested 1	0#, set at 14,5' th 900 sxs Reg on 2-18-66. Cer	78!. nented
Ran 4550 Top of 1 4% Gel, 7-5/8" 1 pressure	(117 joints iner set insi salt saturate iner from 14, for 30 minut	s) 7-5/8" liner, P-1 de 10-3/4" casing a ed and 1# Mud Kill p 578' to 10.028'. W	10 & N-80, 39# & 33.70	0#, set at 14,5' th 900 sxs Reg on 2-18-66. Cer	78!. nented
Ran 4550 Top of 1 4% Gel, 7-5/8" 1	(117 joints iner set insi salt saturate iner from 14, for 30 minut	s) 7-5/8" liner, P-1 de 10-3/4" casing a ed and 1# Mud Kill p 578' to 10.028'. W	10 & N-80, 39# & 33.70 t 10,028. Cemented wi er sx. POB 12:15 PM o OC 48 hours. Tested 1	0#, set at 14,5' th 900 sxs Reg on 2-18-66. Cer	78!. nented
Ran 4550 Top of 1 4% Gel, 7-5/8" 1 pressure	(117 joints iner set insi salt saturate iner from 14, for 30 minut	s) 7-5/8" liner, P-1 de 10-3/4" casing a ed and 1# Mud Kill p 578' to 10.028'. W	10 & N-80, 39# & 33.70 t 10,028. Cemented wi er sx. POB 12:15 PM o OC 48 hours. Tested 1	0#, set at 14,5' th 900 sxs Reg on 2-18-66. Cer	78!. nented
Ran 4550 Top of 1 4% Gel, 7-5/8" 1 pressure	(117 joints iner set insi salt saturate iner from 14, for 30 minut	s) 7-5/8" liner, P-1 de 10-3/4" casing a ed and 1# Mud Kill p 578' to 10.028'. W	10 & N-80, 39# & 33.70 t 10,028. Cemented wi er sx. POB 12:15 PM o OC 48 hours. Tested 1	0#, set at 14,5' th 900 sxs Reg on 2-18-66. Cer	78!. nented
Ran 4550 Top of 1 4% Gel, 7-5/8" 1 pressure	(117 joints iner set insi salt saturate iner from 14, for 30 minut	s) 7-5/8" liner, P-1 de 10-3/4" casing a ed and 1# Mud Kill p 578' to 10.028'. W	10 & N-80, 39# & 33.70 t 10,028. Cemented wi er sx. POB 12:15 PM o OC 48 hours. Tested 1	0#, set at 14,5' th 900 sxs Reg on 2-18-66. Cer	78!. nented
Ran 4550 Top of 1 4% Gel, 7-5/8" 1 pressure	(117 joints iner set insi salt saturate iner from 14, for 30 minut	s) 7-5/8" liner, P-1 de 10-3/4" casing a ed and 1# Mud Kill p 578' to 10.028'. W	10 & N-80, 39# & 33.70 t 10,028. Cemented wi er sx. POB 12:15 PM o OC 48 hours. Tested 1	0#, set at 14,5' th 900 sxs Reg on 2-18-66. Cer	78!. nented
Ran 4550 Top of 1 4% Gel, 7-5/8" 1 pressure	(117 joints iner set insi salt saturate iner from 14, for 30 minut	s) 7-5/8" liner, P-1 de 10-3/4" casing a ed and 1# Mud Kill p 578' to 10.028'. W	10 & N-80, 39# & 33.70 t 10,028. Cemented wi er sx. POB 12:15 PM o OC 48 hours. Tested 1	0#, set at 14,5' th 900 sxs Reg on 2-18-66. Cer	78!. nented
Ran 4550 Top of 1 4% Gel, 7-5/8" 1 pressure	(117 joints iner set insi salt saturate iner from 14, for 30 minut	s) 7-5/8" liner, P-1 de 10-3/4" casing a ed and 1# Mud Kill p 578' to 10.028'. W	10 & N-80, 39# & 33.70 t 10,028. Cemented wi er sx. POB 12:15 PM o OC 48 hours. Tested 1	0#, set at 14,5' th 900 sxs Reg on 2-18-66. Cer	78!. nented
Ran 4550 Top of 1 4% Gel, 7-5/8" 1 pressure	(117 joints iner set insi salt saturate iner from 14, for 30 minut	s) 7-5/8" liner, P-1 de 10-3/4" casing a ed and 1# Mud Kill p 578' to 10.028'. W	10 & N-80, 39# & 33.70 t 10,028. Cemented wi er sx. POB 12:15 PM o OC 48 hours. Tested 1	0#, set at 14,5' th 900 sxs Reg on 2-18-66. Cer	78!. nented
Ran 4550 Top of 1 4% Gel, 7-5/8" 1 pressure	(117 joints iner set insi salt saturate iner from 14, for 30 minut	s) 7-5/8" liner, P-1 de 10-3/4" casing a ed and 1# Mud Kill p 578' to 10.028'. W	10 & N-80, 39# & 33.70 t 10,028. Cemented wi er sx. POB 12:15 PM o OC 48 hours. Tested 1	0#, set at 14,5' th 900 sxs Reg on 2-18-66. Cer	78!. nented
Ran 4550 Top of 1 4% Gel, 7-5/8" 1 pressure	(117 joints iner set insi salt saturate iner from 14, for 30 minut	s) 7-5/8" liner, P-1 de 10-3/4" casing a ed and 1# Mud Kill p 578' to 10.028'. W	10 & N-80, 39# & 33.70 t 10,028. Cemented wi er sx. POB 12:15 PM o OC 48 hours. Tested 1	0#, set at 14,5' th 900 sxs Reg on 2-18-66. Cer	78!. nented
Ran 4550 Top of 1 4% Gel, 7-5/8" 1 pressure	(117 joints iner set insi salt saturate iner from 14, for 30 minut	s) 7-5/8" liner, P-1 de 10-3/4" casing a ed and 1# Mud Kill p 578' to 10.028'. W	10 & N-80, 39# & 33.70 t 10,028. Cemented wi er sx. POB 12:15 PM o OC 48 hours. Tested 1	0#, set at 14,5' th 900 sxs Reg on 2-18-66. Cer	78!. nented
Ran 4550 Top of 1 4% Gel, 7-5/8" 1 pressure	(117 joints iner set insi salt saturate iner from 14, for 30 minut	s) 7-5/8" liner, P-1 de 10-3/4" casing a ed and 1# Mud Kill p 578' to 10.028'. W	10 & N-80, 39# & 33.70 t 10,028. Cemented wi er sx. POB 12:15 PM o OC 48 hours. Tested 1	0#, set at 14,5' th 900 sxs Reg on 2-18-66. Cer	78!. nented
Ran 4550 Top of 1 4% Gel, 7-5/8" 1 pressure Drilling	(117 joints iner set insi salt saturate iner from 14, for 30 minut	s) 7-5/8" liner, P-1 de 10-3/4" casing a ed and 1# Mud Kill p 578' to 10,028'. W es - no drop in pre	10 & N-80, 39# & 33.70 t 10,028. Cemented wi er sx. POB 12:15 PM o OC 48 hours. Tested 1	0#, set at 14,5' th 900 sxs Reg on 2-18-66. Cer	78!. nented
Ran 4550 Top of 1 4% Gel, 7-5/8" 1 pressure Drilling	(117 joints iner set insi salt saturate iner from 14, for 30 minut	s) 7-5/8" liner, P-1 de 10-3/4" casing a ed and 1# Mud Kill p 578' to 10,028'. W es - no drop in pre	10 & N-80, 39# & 33.70 t 10,028. Cemented wi er sx. POB 12:15 PM o OC 48 hours. Tested 1	0#, set at 14,5' th 900 sxs Reg on 2-18-66. Cer	78!. nented
Ran 4550 Top of 1 4% Gel, 7-5/8" 1 pressure Drilling	(117 joints iner set insi salt saturate iner from 14, for 30 minut	s) 7-5/8" liner, P-1 de 10-3/4" casing a ed and 1# Mud Kill p 578' to 10,028'. W es - no drop in pre	10 & N-80, 39# & 33.70 t 10,028. Cemented wi er sx. POB 12:15 PM o OC 48 hours. Tested 1	0#, set at 14,5' th 900 sxs Reg on 2-18-66. Cer	78!. nented
Ran 4550 Top of 1 4% Gel, 7-5/8" 1 pressure Drilling	(117 joints iner set insi salt saturate iner from 14, for 30 minut	s) 7-5/8" liner, P-1 de 10-3/4" casing a ed and 1# Mud Kill p 578' to 10,028'. W es - no drop in pre	10 & N-80, 39# & 33.70 t 10,028. Cemented wi er sx. POB 12:15 PM o OC 48 hours. Tested 1 ssure. Drilled plug a	O#, set at 14,5' th 900 sxs Reg on 2-18-66. Cer iner with 1000/ t 12:00 PM 2-20	78!. nented
Ran 4550 Top of 1 4% Gel, 7-5/8" 1 pressure Drilling S. I hereby certif SIGNED (This space fo APPROVED B	y that the foregoing in , that the foregoing in , for 30 minut	s) 7-5/8" liner, P-1 de 10-3/4" casing a ed and 1# Mud Kill p 578' to 10,028'. W es - no drop in pre s true and correct 	10 & N-80, 39# & 33.70 t 10,028. Cemented wi er sx. POB 12:15 PM o OC 48 hours. Tested 1 ssure. Drilled plug a	O#, set at 14,5' th 900 sxs Reg on 2-18-66. Cer iner with 1000/ t 12:00 PM 2-20	78!. nented
Ran 4550 Top of 1 4% Gel, 7-5/8" 1 pressure Drilling S. I hereby certif SIGNED (This space fo APPROVED B	y that the foregoing in r Federal or State official	s) 7-5/8" liner, P-1 de 10-3/4" casing a ed and 1# Mud Kill p 578' to 10,028'. W es - no drop in pre s true and correct 	10 & N-80, 39# & 33.70 t 10,028. Cemented wi er sx. POB 12:15 PM o OC 48 hours. Tested 1 ssure. Drilled plug a	O#, set at 14,5' th 900 sxs Reg on 2-18-66. Cer iner with 1000/ t 12:00 PM 2-20	78!. nented
Ran 4550 Top of 1 4% Gel, 7-5/8" 1 pressure Drilling S. I hereby certif SIGNED (This space fo APPROVED B	y that the foregoing in , that the foregoing in , for 30 minut	s) 7-5/8" liner, P-1 de 10-3/4" casing a ed and 1# Mud Kill p 578' to 10,028'. W es - no drop in pre s true and correct 	10 & N-80, 39# & 33.70 t 10,028. Cemented wi er sx. POB 12:15 PM o OC 48 hours. Tested 1 ssure. Drilled plug a	O#, set at 14,5' th 900 sxs Reg on 2-18-66. Cer iner with 1000/ t 12:00 PM 2-20	78!. nented

.

ACTING DISTRICT ENGINEER