

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPI — TB*
(Other instructions
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-066096

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)HOBB'S OFFICE U.S.G.S.
MAY 17 10 48 AM '66

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Dry Hole		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR D. H. Ford & B. L. Haynie		8. FARM OR LEASE NAME Federal #3	
3. ADDRESS OF OPERATOR P. O. Box 1209, Roswell, New Mexico		9. WELL NO. 1.	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 330' fr N 1/4 & 330' fr E 1/4 of Sec. 10, T 26 S, R 35 E, Lea County, New Mexico.		10. FIELD AND POOL, OR WILDCAT Wildcat	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 10, T 26 S, R 35 E	
15. ELEVATIONS (Show whether DF, RT, GR, etc.)		12. COUNTY OR PARISH Lea	
		13. STATE N. M.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Drilled to total depth of 5276'; cored from 5226' - 5276', no shows of oil or gas recovered; ran logs; propose to plug & abandon, setting cement plugs as follows:

1. 100' plug from 5276 - 5176'
2. 100' plug from 1500' - 1400'
3. 100' plug from 1150' - 1050'
4. 100' plug from in & out 8 5/8" shoe
5. Surface plug with 10 sacks.

Handwritten note: *all plugs set*

Verbal approval to plug was secured by phone on 5/9/66 from J. L. Gordon, Hobbs Office of U.S.G.S. to plug using the above plugging program.

18. I hereby certify that the foregoing is true and correct

SIGNED R. L. Haynie TITLE _____DATE 5/9/66

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____
CONDITIONS OF APPROVAL, IF ANY:

APPROVED

MAY 10 1966

*See Instructions on Reverse Side

J. L. GORDON
ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 11: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.