

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TR
(Other instruction
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Conoco Inc.		8. FARM OR LEASE NAME Eaves B-1
3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, New Mexico 88240		9. WELL NO. 12
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FNL & 660' FWL - Unit Letter D		10. FIELD AND POOL, OR WILDCAT Scarborough y-5R
14. PERMIT NO. 30-025-21862		11. SEC., T., R., M., OR BLM, AND SURVEY OR AREA 31-26S-37E
15. ELEVATIONS (Show whether DF, RT, CR, etc.)		12. COUNTY OR PARISH Lea
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

MIRU. Run csq scraper. Set CIBP at 3125'. Mty mud & circ hole clean. Spot 30 sxs class "C" cement on top of CIBP. Pull 25 stds & WOC. Tag plug at 2687'. Pull up to 1523' & spot 23 sxs cement. Perf at 460' w/4 spf. Well on vacuum. Pumped 60 BW, hole would not load. Squeeze 135 sxs cement, close well in. WOC 4 hrs. Press test csq. Squeeze 125 sxs cement & circulate cement to surface. Install P&A marker on 5/5/88

RECEIVED
JUN 23 11 00 AM '88
OFFICE OF THE
ADMINISTRATIVE SUPERVISOR

18. I hereby certify that the foregoing is true and correct

SIGNED W. F. Finney

TITLE Administrative Supervisor

DATE June 27, 1988

FOR OFFICIAL USE ONLY (For Bureau or State office use)

APPROVED BY W. F. Finney RESOURCES

TITLE _____

DATE 7-19-88

CONDITIONS OF APPROVAL, IF ANY:

1. This approval is valid only for the purpose stated and shall be void if the purpose is not stated.

*See instructions on Reverse Side

Penalty: Whoever knowingly and willfully makes or causes to be made to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

N RLM-Carlstad (6) ARCE (2) Amore (2) Chace (1) Lila