rm 3160-5 ine 1990)

UNITLL STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED	
Budget Bureau No. 1004	-0135
Fxnires: March 31, 19	93

5. Lease Designation and Serial No.

NMNM7951 SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE Type of Well 8. Well Name and No. Oil Gas Well U Other Leonard Federal #8 . Name of Operator 9. API Well No. Bettis, Boyle & Stovall 300252188100\$1 3. Address and Telephone No. P.O. Box 1240, Graham, TX 76450 10. Field and Pool, or Exploratory Area 817-549-0780 Rhodes-Y-5R Gui 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State Cout m Lea Co., NM 660' FSL & 660' FWL of Sec. 14, T26S, R37E CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION Change of Plans Abandonment Notice of Intent New Construction Recompletion Non-Routine Fracturing Plugging Back ___ Subsequent Report Water Shut-Off Casing Repair Conversion to Injection Altering Casing Final Abandonment Notice Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Notified Mr. Adam Salameh with the Carlsbad OCD that we were not going to pull 9/15/92 the 4-1/2" but would leave it in place. He gave me permission to change the second step in our plugging procedure to be perf @ 1100' and squeeze. Tag plug Approved as to plugging of the and pull NO pipe. Liability enter bond is retained to surface restoration is completed. MIRU Baber Well Service to plug and abandon the Leonard Federal #8. RI & opened 9/15/92 well. Pull and load rods, pump. Remove wellhead cap & packing, POOH with 96 jts. 2-3/8" tbg.. RIH with 4-1/2 CIBP & tbg. to 2650'. Set CIBP. Closed well in. SDFN. RU to pump, circulated hole with salt gel from 2650' to surface. Spotted 9/16/92 4 sx. cement on top of CIBP. POOH with tbg.. RU wireline, RIH with 4 shot string, perf. 4-1/2" casing @ 1100'. RIH with tbg. to 1050', RU to pump, establish injection rate, squeezed 50 sx. cement, POOH with tbg. WOC overnight. Closed well in, SDFN. RIH with tbg. & tagged cement plug @ 950'. Pull down tbg. to 400', RU to 9/17/92 pump, circ. cement to surface with 35 sx. cement. POOH. Cut off wellhead Cleaned location & moved off. 14. I hereby certify that the foregoing is true and correct Production Analyst Signed (This space for Federal or State office use) Approved by ______ Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.