

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. NMMS 8-8324	
7. Unit Agreement Name None	
8. Farm or Lease Name Marathon State	
9. Well No. 1 (one)	
10. Field and Pool, or Wildcat Treasta Draw	
12. County Lea	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator T.F. Hodge
3. Address of Operator 308 No. Colorado Midland, Texas 79701
4. Location of Well UNIT LETTER D 990 FEET FROM THE North LINE AND 990 FEET FROM THE West LINE, SECTION 2 TOWNSHIP 24-S RANGE 32-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3622 Ground level

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Recommend plugs

- No. 1 (one) 4960' Td 30 (Thirty) sacks
No. 2 (two) bottom 25 (twenty five) sacks base of salt 4050'
No. 3 (three) bottom 25 (twenty five) sacks top of salt 3450'
No. 4 (four) bottom 10 (ten) sacks at 990' 16' below 7" shoe
No. 5 (five) in top of 7" casing with well marker as required 5 sacks

Hole to be loaded with mud ladden material
Location to be cleaned to State regulations

25 SXS

10 SXS

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED H.T. Green	TITLE Production superintendent	DATE 4/14/1970
APPROVED BY [Signature]	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		