

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0448921-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

- - -

7. UNIT AGREEMENT NAME

Mexico-Fed "P"

8. FARM OR LEASE NAME

Mexico-Fed "P"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Section 21-26S-35E

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

1.

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Skelly Oil Company

3. ADDRESS OF OPERATOR

P. O. Box 730 - Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)
At surface

1980' P.W. & 1980' P.W. Section 21-26S-35E

14. PERMIT NO.

- - -

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3178' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) **Plugback & Perforate**

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

X

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The following work has been completed as approved by U.S.G.S. on Form 98331C dated 12-30-68.

- 1) Spotted cement plug at top of Silurian-Devonian 19,269-18,766'.
- 2) Spotted cement plug over casing shoe 18,650-17,932'.
- 3) Set 7-5/8" Drill Bridge plug in liner at 16,000' and filled with cement to 15,994'.
- 4) Perforated 7-5/8" OD liner 15,666-15,670'. Squeezed perforations. Drilled out cement plug to 15,640' inside 7-5/8" OD casing.
- 5) Perforated 7-5/8" OD Liner 15,500-504'. Several attempts were made to squeeze perforations. After the last squeeze, perforations were tested at 6500# for 15 minutes with no pressure loss. Top of cement 15,274'. Drilled out cement 15,274-15,506'; washed 15,506'; 600#.
- 6) Perforated 7-5/8" liner 15,565-15,616' (Atoka). Treat with approximately 4,000 gallons. Test.

18. I hereby certify that the foregoing is true and correct

SIGNED

(ORIGINAL)
SIGNED

V. E. Fletcher

TITLE **District Production Manager**

DATE **1-15-69**

(This space for Federal or State office use)

APPROVED BY

TITLE

APPROVED

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

J. L. GORDON
ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963—O-685229

GPO 8 37-499

867-851