Form 3160-5 (June 1990)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

| M. OIL CONS. COMM                  | 22101z |
|------------------------------------|--------|
| P.O. BOX 1980<br>HOBBS. NEW MEXICO | 88240  |
| HODDS, January                     |        |

Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No. LC 030187

| SUNDRY | NOTICES | AND | REPORT | S ON | WEL | LS | ; |
|--------|---------|-----|--------|------|-----|----|---|
| 00.00  |         |     |        |      |     | •  |   |

Do not use this form for proposals to drill or deepen or reentry to a different reservoir.

| Ì | 6. If Indian, Allottee or Tribe Name    |
|---|---|
| ١ | N/A                                     |
|   | 7. If Unit or CA, Agreement Designation |
| ╡ | N/A                                     |

| Do not use this form for proposals to drill or de   | OR PERMIT-" for such proposals                                | N/A   |
|---|---|---|
|   | IBMIT IN TRIPLICATE   | 7. If Unit or CA, Agreement Designation N/A   |
| 1. Type of well Gas Other   |   | 8. Well Name and No.  C. E. LAMUNYON NO. 27   |
| 2. Name of Operator ARCH PETROLEUM, INC.  |   | 9. API Well No.<br>30-025-22433   |
| 3. Address and Telephone No. 777 Taylor St., Suite II-A, Ft. Worth, T   | X 76102 (817) 332-9209  | 10. Field and Pool, or Exploratory Area TEAGUE BLINEBRY   |
| 4. Location of Well (Footage, Sec., T., R., M., or Survey Description<br>1980' FNL 2130' FWL, Unit F, Section | )   | 11. County or Parish, State   |
| CHECK APPROPRIATE BO  | OX(S) TO INDICATE NATURE OF NOTICE, R                         | EPORT, OR OTHER DATA  |
| 12 TYPE OF SUBMISSION Notice of Intent  | Abendonment   | Change of Plans New Construction Non-Routine Fracturing   |
| Subsequent Report   | Plugging Back Casing Repair                                   | Water Shut-Off Conversion to Injection  |
| Final Abandonment Notice  | Attering Casing    X   Other ADD PERF, ACIDIZE AND FRAC TREAT | Dispose Water (Note: hapent results of multiple completion on Well Completion or Recompletion Report and Log form.) |

We propose to:

POOH with producing equipment. NDWH NUBOP. Check for fill and clean out if needed. Add perfs to Blinebry Acidize and sand frac all perfs. Flow back. NDBOP NUWH. GIH with producing equipment. Place well on production.



|   |  | / /                      |
|---|--|--------------------------|
| 14. I hereby cegity that the forgoing is true and correct Signed Salue Scales | Title Production Analyst                                     | Date 3/2/95              |
| (DRIG. SGD.) JOE G. LARA  | PETROLEUM ENGINEER   | Date3/20/95              |
| Conditions of approval, if any:   | the second analysis of the United States any false, fictious | or traudulent statements |



PENED