

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPL
(Other instructions
verse side)

E*
re

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> Plug and Abandon		5. LEASE DESIGNATION AND SERIAL NO. LC 062132
2. NAME OF OPERATOR SINCLAIR OIL & GAS COMPANY		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Box 1920, Hobbs, New Mexico 88240		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' from the South and West lines.		8. FARM OR LEASE NAME Delooey Federal
14. PERMIT NO.		9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.)		10. FIELD AND POOL, OR WILDCAT Wildcat-Bell Canyon
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 11-T26S-R35E
		12. COUNTY OR PARISH Lea
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) * TD 5486'

5-6-68 Filled hole w/mud laden material and spotted 30 sacks cement (100' plug across top of Delaware sand 5100' to 5200'). Spotted 30 sacks cement plug above salt 900' to 1000'. Spotted 30 sacks cement plug bottom of 8-5/8"OD surface casing 235' to 355'. Spotted 20 sacks cement plug 0-50' in top of 8-5/8"OD surface casing and cellar, install regulation dry hole marker, cleaned and levelled location. Plugged and Abandoned effective 5-6-68. No shows of oil or gas.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Superintendent

DATE 5-7-68

(This space for Federal or State office use)

APPROVED BY

TITLE

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

SEP 21 1968

*See Instructions on Reverse Side

Original: USGS, Hobbs
cc: Regional Office
cc: file

J L GORDON
ACTING DISTRICT ENGINEER