

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/></p>
<p>1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-</p>		<p>5. State Oil & Gas Lease No.</p>
<p>2. Name of Operator IMPERIAL AMERICAN MANAGEMENT COMPANY</p>		<p>7. Unit Agreement Name</p>
<p>3. Address of Operator 215 Mid America Building, Midland, Texas 79701</p>		<p>8. Farm or Lease Name Seeton</p>
<p>4. Location of Well UNIT LETTER G 2310 FEET FROM THE North LINE AND 1650 FEET FROM THE East LINE, SECTION 21 TOWNSHIP 23S RANGE 37E NMPM.</p>		<p>9. Well No. 1</p>
<p>15. Elevation (Show whether DF, RT, GR, etc.) 3298 GR</p>		<p>10. Field and Pool, or Wildcat Imperial Tubb Drinkard</p>
<p>12. County Lea</p>		

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

<p>NOTICE OF INTENTION TO:</p> <p>PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/></p>		<p>SUBSEQUENT REPORT OF:</p> <p>REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/></p> <p>COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/></p> <p>CASING TEST AND CEMENT JOB <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/> Status Report <input checked="" type="checkbox"/></p>	
--	--	--	--

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This zone T/A with DR plug In Baker Model D Packer at 5950' on 2-18-71. The zone may be re-activated after completion of necessary reservoir study.

The ownership of this property is in reorganization under Chapter X of the Federal Bankruptcy Act. The Trustee of the corporation has not been able to provide funds for the necessary examination of workover potential. It is anticipated that the company's reorganization will be complete in the latter quarter of 1975 and that funds will then be available to examine the property for workover possibilities and to perform the workover if justified. We request that adequate time be given for this contingency prior to the forced plugging and abandonment of this zone.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed R. S. Hunter TITLE Agent DATE 11/11/74

APPROVED BY Joe D. Raley TITLE Dist. I, Supv. DATE 11/11/74

CONDITIONS OF APPROVAL, IF ANY: