14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3336 GR	12. COUNTY OR PARISE	N.M.	
	1980 FML & 1980 FEL	Sec. 18, T-2		
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface		Langlic Mattix 11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA		
507 111	dland Savings Bldg., Midland, Texas 79701	10 FIELD AND POOL O	10. FIELD AND POOL, OR WILDCAT	
3. Address of	al-American Management Co.	9. WELL NO.		
2. NAME OF OR		Hughes "A"		
WELL X	GAS WELL OTHER	8. FARM OR LEASE NAME		
1.		7. UNIT AGREEMENT NAME		
(Do not	SUNDRY NOTICES AND REPORTS ON WELLS use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTER	OR TRIBE NAME	
	DEPARTMEN OF THE INTERIOR VOTHE BILLE (OTHER BILLE) GEOLOGICAL SURVEY	5. LEASE DESIGNATION NM - 2244		
Form 9-331 (May 1963)	UNITED STATES SUBMIT IN TRIPLIC TO	Buaget Burea	u No. 42-R1424.	

(Other)

SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: REPAIRING WELL PULL OR ALTER CASING WATER SHUT-OFF TEST WATER SHUT-OFF ALTERING CASING FRACTURE TREATMENT MULTIPLE COMPLETE FRACTURE TREAT

ABANDON MENT* SHOOTING OR ACIDIZING ABANDON* SHOOT OR ACIDIZE er) Woll Status
(Norm: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) CHANGE PLANS REPAIR WELL

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent to this work.) *

Subject well is shut-in and temporariby abandoned. Testing allowable was requested to permit emptying the stock tanks.

18. I hereby certify that the foregoing is true and correct 8-26-70 Operations Supt. DATE TITLE (This space for Federal or State office use) TITLE APPROVED BY CONDITIONS OF APPROVAL, IF ANY: 3 1970 5=7 *See Instructions on Reverse Side S. LEULUGIUME SUINVEY HOBBS, NEW MEXICO

REFEREN

OIL CONSERVATION COMM.