

NEW MEXICO OIL CONSERVATION COMMISSION

O+2 - NMOC  
1 - File  
1 - Engineer (PB)  
1 - Foreman

SUMMARY NOTICES AND REPORTS ON WELLS

5a. Indicate Type of Lease

State ☐ Free ☒

5. State Oil & Gas Lease No.

6. Name of Lease Holder

J. C. Johnson

9. Well No.

6

10. Field and Pool, or Wildcat

Langlie Mattix

15. Elevation (Show whether DF, RT, GR, etc.)

12. County

Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☒  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐

CHANGE PLANS ☐

OTHER ☐

REMEDIAL WORK ☐

COMMENCE DRILLING OPER.

CASING TEST AND CEMENT JOBS ☐

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

1. Describe or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed

**ILLEGIBLE**

J. C. Johnson Well No. 6  
Workover Procedure

1. Rig up pulling unit and install BOP.
2. Pull rods and tubing.
3. GIH with casing gun and perforate the following intervals with 1 spf  
3346-50; 3380-86; 3462-66; 3468-74; 3495-98; 3500-02; 3504-10; 3533-38;  
3566-70. (49 holes).
4. GIH with 2 3/8" tubing and packer.
5. Set packer at + 3300'.
6. Acidize total interval, 3346'-3585', as per service company's recommendations.
7. POH with tubing and packer.
8. Return well to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED BY [Signature] TITLE Area Superintendent

DATE 4/3/81

COPIES OF APPLICATION, IF ANY:

TITLE DATE

OIL CONSERVATION DIV.

APR 16 '81

RECEIVED