

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLE  
(Other instructions  
verse side)

FE-  
Fe-

Form approved.  
Budget Bureau No. 42-R1424.  
6. LEASE DESIGNATION AND SERIAL NO.

81-14164

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER Dry Hole

2. NAME OF OPERATOR  
Gulf Oil Corporation

3. ADDRESS OF OPERATOR  
Box 670, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

1980' FN & WL, Section 5, 24-S, 35-E

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Wilson Federal Com

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Undesignated

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec 5, 24-S, 35-E

12. COUNTY OR PARISH 13. STATE

Lea New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, OR, etc.)

3455' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON\* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) Plugged and abandoned.

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☒

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

14,248' TD, 14,190' PB.

Spotted 35 sack cement plug on top of Otis WB packer at 13,700'. Loaded hole with abandonment mud. Set CI BP at 11,700' and capped with 35 sack cement plug to 11,537'. Spotted 35 sack cement plug from 9124' to 8961', across Bone Springs; spotted 35 sack cement plug from 5500' to 5337', across DV tool at 5400'. Cut and recovered 7" casing from 4167' to 2988'. Spotted 55 sack cement plug from 3036' to 2936', across 9-5/8" stub at 2988'. Spotted 70 sack cement plug from 900' to 800', across top of Anhydrite; 75 sack cement plug from 500' to 400', across 13-3/8" shoe at 436' and spotted 40 sack cement plug from 50' to surface. Plugged and abandoned August 7, 1974. Will advise when location is ready for your inspection.

18. I hereby certify that the foregoing is true and correct

SIGNED

*[Signature]*

TITLE Area Engineer

DATE August 8, 1974

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*[Signature]*