

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-5803
7. Unit Agreement Name
8. Farm or Lease Name State
9. Well No. 1
10. Field and Pool, or Wildcat East Mason Delaware
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator William F. Grauten
3. Address of Operator c/o Oil Reports & Gas Services, Inc., Box 753, Hobbs, New Mexico 88240
4. Location of Well UNIT LETTER L , 1666 FEET FROM THE South LINE AND 330 FEET FROM THE West LINE, SECTION 16 TOWNSHIP 26 S RANGE 32 E N.M.P.M.
11. Elevation (Show whether DF, RT, GR, etc.) 3162 GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

To confirm verbal approval to plug as follows:

Set Cast Iron Bridge Plug at 4375 & cap with 3 (35' min)
sacks cement
100' cement plug across 4 1/2" casing stub at
approximately 3400
100' cement plug at top Salt at 1130
100' cement plug across 8 5/8" casing shoe at
625
10 sacks at surface with regulation marker
Mud between all plugs.
Location to be cleaned and levelled.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John Runyan TITLE Agent DATE 8/14/75

Copied Signed By
John Runyan
Geologist

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: