			Form C-10:		
DISTRIBUTION SANTA FE	←		Supersedes C+102 and		
	NEW MEXICO OIL CONS	SERVATION COMMISSION	Effective)		
Fi.E					
U.S.G.S.	 		5a. Indicate T	ype of Lease	
	<u> </u>		State 🗶	Fee	
OF ERATOR			5, State Oil &	Gas Lease No.	
			K	-5 803	
SUNDRY NOTICES AND REPORTS ON WELLS 100 NGT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DESPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. 100 NGT USE MAPPLICATION FOR PERMIT - " (FORM 0-101) FOR SUCH PROPOSALS."					
O(L GAS WELL WELL WELL	OTHER.		7. Unit Agreen	nent Name	
2. Tame of operator			8. Farm or Lea		
William F. Grauten 3. A Firesip of Spector				State	
/a 043 Banant & 0	Second of Total Total Total		9. Well No.		
2/0 Ull Reports & Gas 4. Location of Well	Services, Inc., Box 763, E	locbs, New Mexico 8824			
		10. Field and Pool, or Williagt			
UNIT LETTER	UNIT LETTER L . 1666 FEET FROM THE SOUTH LINE AND 330 FEET		FROM East Mason Delaware		
THE Wast LINE,	ECTION 16 TOWNSHIP 20 S	RANGE 32 LI NN	1PM.		
	15. Elevation (Show whether	DE RT CR and		71. H.	
	3162		12. County		
			Lea		
NOTICE C	ck Appropriate Box To Indicate N FINTENTION TO:		Other Data ENT REPORT O	F:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL ADEX	Διτ	ERING CASING	
	FEOG AND ABANDON			EMING CASING	
TEMPORARILY ABANDON	AESG AND ABACOON				
TEMPORABLY ABANDON PULL OR ALTER CASING	CHANGE PLANE	COMMENCE OR LLING OPNS.		G ANE ABANDONVIENT	
				G ANE ABANDONMENT	
PULL OR ALTER CASING		COMMENCE OR LLING OPNS. CASING TEST AND CEMENT JQB	PLUI		
PULL OR ALTER CASING OTHER 17. Pescrite i ro; sped or Complet	CHANGE P.ANE	casing at 4489 with with 6# salt per	PLUI		
THER 2THER 17. **escrite* is ro; seed of Complet cork, SEE RULE 1103.	Cemented 4 1/2" 10.5# K-55 200 sacks Class "C" cement sack. Plug down 8:00 Am 8 Tested casing with 1500# f	casing at 4489 with with 6# salt per 1/2/75. WOC to 8/6/75. or 30 minutes, test	ding estimated date o		
OTHER 17. Jesorite i ro; sued or Complet work, SEE RULE 1103. 6. I hereby certify that the inform IGN ID	Cemented 4 1/2" 10.5# K-55 200 sacks Class "C" cement sack. Plug down 8:00 Am 8 Tested casing with 1500# f 0.K. Top cement 3400'.	casing at 4489 with with 6# salt per 1/2/75. WOC to 8/6/75. or 30 minutes, test	ding estimated date o	f starting any proposed	
27HER	Cemented 4 1/2" 10.5# K-55 200 sacks Class "C" cement sack. Plug down 8:00 Am 8 Tested casing with 1500# f 0.K. Top cement 3400".	casing at 4489 with with 6# salt per 1/2/75. WOC to 8/6/75. or 30 minutes, test	ding estimated date o	f starting any proposed	