

Revised 2-21-87

WELL NAME: Hughes Federal #3
FIELD: Langlie Mattix
ELEVATION: 3304' GL
LOCATION: 660' FSL & 2080' FWL Sec. 17, T-23-S,
R-37-E, Lea County, New Mexico
CASING DETAIL: Surface: 8-5/8" @ 500'. Cmt w/320 sx.
Production: 4-1/2" 9.5# @ 3725'. Cmt
w/1200 sx.
PERFS: 3498-3641'
TUBING DETAIL: 110 jts (3339') 2-3/8" Salta Lined w/
4-1/2" AD-1 pkr @ 3339'.

** PLUGGING PROCEDURE **

- 1) MIRU PU.
- 2) NU BOP.
- 3) Attempt to unseat AD-1 pkr. If any trouble is encountered, proceed to Step #4. If not, TOH & LD tbg & pkr & proceed w/Step #6.
- 4) RU WL. Cut off tbg @ 3329' (10' above pkr) & TOH. LD tbg.
- 5) TIH w/work string & pump 10 sx cement on top of pkr. Proceed to Step #8. Tag plug.
- 6) TIH w/workstring to ETD of 3650±.
- 7) RU Western Co. & pump 25 sx plug @ 3650'. Tag plug @ 3450'.
- 8) Pump 10 sx (100' plug) @ 2500' to 2400'.
- 9) Pump 10 sx (100' plug) @ 1000' to 900'.
- 10) Pump 10 sx @ surface.
- 11) Install pipe marker.
- 12) Clean location.

Approved By:

William G. Murray
William G. Murray
Div. Prod. Supt.

Date:

2-21-87

RECEIVED
FEB 26 1987
OCD
HOBBS OFFICE