## TENNECO OIL COMPANY

## PROGNOSIS TO DRILL AND COMPLETE

DISTRICT: Rocky Mountain

<u>DATE</u>:

LEASE: Leonard Brothers

LOCATION: 1650' FSL & 990' FEL Section 13, T 26S, R 37E Lea County, New Mexico WELL NO: 2

FIELD: Queen Penrose

ESTIMATED ELEVATION: GL 2992

ESTIMATED TOTAL DEPTH: 3900'

PROJECTED HORIZON: Leonard Queen

DRILLING, CASING AND CEMENT PROGRAM:

- 1. INIRURT
- 2. Drill 12-1/4" hole ± 500'
- 3. Set and cement 8-5/8" 24 #1 ft. K-55 surface casing at <sup>±</sup> 500. Run sufficient cement to circ.
- 4. Nipple up BOP, test casing to 500 PSI for 30 min.
- 5. Drill out shoe with 7-7/8" bit and drill to TD.
- 6. Log as specified else-where in this prognosis.
- 7. Condition hole and run 5-1/2" casing if productive. Cement first stage through guide shoe with sufficient cement to cover 500 feet above the Queen. Cement second stage through stage collar @ 1200 with sufficient quantity to bring cement into the surface csg. Volumes to be calculated from caliper logs.
- 8. Estimated formation tops.

Anyhydrite Salt	1170	Queen Penrose	3400 (Possible Oil or Gas Bearing Form) 3590 (Possible Oil or Gas Bearing Form)
Yates	2550	Gragburg	
7 Rivers	2910	0 0	

Surface Formation: Oglala (Miocene)

JAN 2: 1977 OIL CONSERVATION CONTINU.