

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on  
reverse side)

COPY TO O.S.C.

Form approved.  
Budget Bureau No. 42-R1424.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. <b>NM 02889</b>
2. NAME OF OPERATOR <b>Continental Oil Company</b>		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR <b>Box 460, Hobbs, N.M. 88240. 11/18/1977</b>		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <b>1980' FSL &amp; 1980' FWL of Sec 12</b>		8. FARM OR LEASE NAME <b>Wimberly</b>
U.S. GEOLOGICAL SURVEY HOBBS, NEW MEXICO		9. WELL NO. <b>8</b>
14. PERMIT NO.		10. FIELD AND POOL, OR WILDCAT <b>Double X Delaware</b>
15. ELEVATIONS (Show whether DF, RT, GR, etc.) <b>3593' GR</b>		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <b>Sec 12 T-24S R-32E</b>
		12. COUNTY OF PARISH <b>Lea</b>
		13. STATE <b>N.M.</b>

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

## SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
(Other) <b>Set 5 1/2" Csg.</b>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

## 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Drilled 7 7/8" hole to TD of 5070'. Ran 129 joints 5 1/2", 14 #, K-55, ST+C csg. Set at 5070' and cemented w/200 SX w/470 gel, 3 #/sk. salt, 270 CaCl<sub>2</sub> + 200 SX cmt. w/ 3 #/sk salt, 270 CaCl<sub>2</sub> + 1/4 #/sk floccle. Plug down at 8:45 pm.  
Waiting on completion rig.

## 18. I hereby certify that the foregoing is true and correct

SIGNED

*Wm. A. Rutledge*

TITLE

*ADMIN. SUPERV.*

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD	
DATE <b>11/21/1977</b>	
U. S. GEOLOGICAL SURVEY HOBBS, NEW MEXICO	

\*See Instructions on Reverse Side

USGS(5), file