

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS	
Use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.	
1. NAME OF OPERATOR	2. LEASE DESIGNATION AND SERIAL NO.
United Gas Search, Inc.	NM-7952
3. ADDRESS OF OPERATOR	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
P. O. Box 755, Hobbs, NM 88241	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)	7. UNIT AGREEMENT NAME
At surface 660' FNL & 1980' <del>FNL</del> <sup>E</sup>	
14. PERMIT NO.	8. FARM OR LEASE NAME
	Leonard Bros. "A"
15. ELEVATIONS (Show whether DF, RT, OR, etc.)	9. WELL NO.
	10. FIELD AND POOL, OR WILDCAT
	South Leonard Queen 38760
	11. SEC., T., R., M., OR BLK. AND SUBST OR AREA
	Sec. 23, T26S, R37E
	12. COUNTY OR PARISH
	Lea
	13. STATE
	NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO

TEST WATER SHUT-OFF	STOP OR ALTER CASING
PERF. TEST TREAT	COMPLETE
SHOOT OR ACIDIZE	ABANDON*
REPAIR WELL	CHANGE PLANT
OTHER	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	REPAIRING WELL
FRAC. TREATMENT	ALTERING CASING
SHOOTING OR ACIDIZING	ABANDONMENT*
(Other) Set Bridge Plug & Test	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETE OPERATIONS. Fully state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.\*

9/14/90 Set retrievable bridge plug at 3502. Treated Queen perms 3402-81 with 2000 gallons 15% acid. Pumped acid water. Shut in waiting on portable tester. 10/17/91 pumped 1 1/2 bbls oil, 40 bbls water in 23 hours, pump stuck. Shut in waiting on Leonard Bros. "A" tank battery repair. 7/1/91 regular pumper left on vacation. Relief pumper found well, bumped pump loose and pumped same into Leonard Federal battery #2. Regular pumper found well pumping 9 AM. 7/16/91 and shut in. Assuming well produced 15 days at rate of 1 1/2 bbls per day, total production for period would be 22.5 bbls. Plans remain to repair the "A" battery and return well to production into separate battery as commingling NM-7951 & NM-7952 is not feasible due to difference in interest. Permission is hereby requested to transfer 22.5 bbls from NM-7951 to NM-7952 when battery repairs are complete in order that proper credit can be given to NM-7952.

18. I hereby certify that the foregoing is true and correct

SIGNED Bunyah Zuber

TITLE President

DATE 8/5/91

(This space for Federal or State office use)

APPROVED BY Chris Jones by Adam Solameh  
CONDITIONS OF APPROVAL, IF ANY:

TITLE REPOSITORY

DATE 8-19-91

\*See Instructions on Reverse Side