Submit 3 Copies To Appropriate District Office <u>District 1</u> 1625 N. French Dr., Hobbs, NM 88240		State of New Mexico Energy, Minerals and Natural Resources			Form C-103 Revised March 25, 1999 WELL API NO.				
District II 811 South First, Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 2040 South Pacheco, Santa Fe, NM 87505	OIL CONSERV 2040 Sou Santa Fe,	ith Pacl	neco		FEE 🔀				
SUNDRY NOTIC (DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.) 1. Type of Well: Oil Well Gas Well	7. Lease Name or Unit AgreementName: MYERS LANGLIE MATTIX UNIT								
2. Name of Operator OXY USA	8. Well No. <b>30</b>								
3. Address of Operator P.O. BOX 5	9. Pool name or Wildcat LANGLIE MATTIX 7RVR-QN-GB								
4. Well Location Unit Letter K: 1980 feet from the South line and 1980 feet from the West line									
Section SO Township ZSS Range STC NMPM County LEA 10. Elevation (Show whether DR, RKB, RT, GR, etc.)									
11. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK	Report or Other I		s 🗆						
	CHANGE PLANS		COMMENCE DRIL	LING OPNS. 🔲	PLUG AND	X			
PULL OR ALTER CASING	MULTIPLE ( COMPLETION		CASING TEST AN CEMENT JOB		ABANDONMENT				
OTHER:			OTHER:						

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

See other side

I hereby certify that the SIGNATURE	e information above is true and	complete to the	best of my knowledge and belies REGULATORY ANALYST	f. DATE_Z\5/0
Type or print name	DAVID STEWART			Telephone No.915-685
(This space for State us APPPROVED BY Conditions of approval	Amel	TITLE	Fid Rep	DATE // - 20
, Gw	W			

,

### MLMU # 30

# 12/13/2000 MIRU

# 12/14/2000

Pump 30 bbls to kill well and NU WH. Pull 15 jts tbg. Tbg stuck. Pumped more water pulled 13 jts tbg. SD

### 12/15/2000

POOH w/pkr and went back with csg scraper to 3467. POOH w/scrapper and back w/tbg and CIBP set at 3467.

# 12/18/2000

Spot 25 sks cmt on CI BP. Circ w/brine gel mud 9.5 lb and POOH w/tbg and WOC. Tag cmt 3227 pull tbg to 2990. Spot 25 sks cement and POOH

#### 12/19/2000

RIH w/tbg and tag at 2728. PU to 1280 spot 25 sks cmt. Tag TOC 1230. PU place bottom at 546 and spot 25 sks cmt POOH SD.

### 12/20/2000

i minich Sterrige

RIH w/tbg and tag 300 spot 10 sks from 100 to surf. RD Clean Location. Well Plugged.

. +