

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	L-6315

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator BTA OIL PRODUCERS	8. Farm or Lease Name Lea, 7406 JV-S
3. Address of Operator 104 South Pecos Midland, Texas 79701	9. Well No. 5
4. Location of Well: UNIT LETTER <u>L</u> <u>2310</u> FEET FROM THE <u>South</u> LINE AND <u>990</u> FEET FROM THE <u>West</u> LINE, SECTION <u>28</u> TOWNSHIP <u>26-S</u> RANGE <u>36-E</u> N.M.P.M.	10. Field and Pool, or Wildcat Comanche State line (Tansill Yates)
11. Elevation (Show whether DF, RT, GR, etc.) 2895' GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-16-81 - Set CIBP @ 3100' Capped w/35' Cmt. Cut & pulled 5½" csg @2217'.

10-17-81 - Set 40 sx cmt plug @ 2247'. WOC 4 hrs.
Tagged plug @ 2043'. Set 50 sx plug @ 1450'.

10-18-81 - Tagged plug @ 1253'. Set 10 sx plug @ Surface. Installed dry hole Marker.
P&A 10-17-81.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. D. Boyce TITLE Administrative Superintendent DATE 10/21/81

APPROVED BY R. D. Boyce TITLE OIL & GAS INSPECTOR DATE SEP 3 1987

CONDITIONS OF APPROVAL, IF ANY: