

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
L-6315	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator BTA OIL PRODUCERS		8. Farm or Lease Name Lea, 7406 JV-S
3. Address of Operator 104 South Pecos Midland, Texas 79701		9. Well No. 5
4. Location of Well UNIT LETTER L 2310 FEET FROM THE South LINE AND 990 FEET FROM THE West LINE, SECTION 28 TOWNSHIP 26-S RANGE 36-E NMPM.		10. Field and Pool, or Wildcat Comanche Stateline, State
15. Elevation (Show whether DF, RT, GR, etc.) 2895'		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set CIBP @ 3100' w/3 sx cmt on top (35')  
Cut & Pull 5½" csg. Top cmt 2363'.  
Set 40 sx Cmt plug across 5½" stub.  
Set 50 sx Cmt plug across 8-5/8" shoe @ 1400'.  
Set 10 sx Cmt plug at Surface.  
Install dry hole marker.

(9.5# Mud Laden Fluid between plugs)

THIS OPERATOR HAS BEEN ADVISED BY THE COMMISSION THAT THE OIL AND GAS CONSERVATION ACT, N.M.S.A. 1978, 72-1-1, PROVIDES THAT THE OIL AND GAS CONSERVATION COMMISSION HAS THE AUTHORITY TO APPROVE, DISAPPROVE, OR CONDITIONALLY APPROVE ANY PROPOSED OPERATION.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. D. Boyce TITLE Administrative Superintendent DATE 6/3/81

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_