

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 26369
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name Government L Com.
2. Name of Operator Enron Oil & Gas Company	8. Well No. 2
3. Address of Operator P. O. Box 2267, Midland, Texas 79702	9. Pool name or Wildcat West Pitchfork Ranch Atoka
4. Well Location Unit Letter <u>K</u> : <u>1980</u> Feet From The <u>south</u> Line and <u>1800</u> Feet From The <u>West</u> Line Section <u>18</u> Township <u>24S</u> Range <u>34E</u> NMPM Lea County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3573' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF: 1/24/90
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-19-90 - Spot 25 sx plug at 13,000' - tagged cement at 13,100'.
9-21-90 - Cut 7-5/8" csg at 7834'
9-27-90 - Set 70 sx plug @ 12,909'. TOH to 7800' & set 50 sx plug across csg stub.
9-28-90 - Set 60 sx plug from 5450' to 5550'
10-2-90 - Cut 10-3/4" casing at 2373'
10-3-90 - TIH to 2425' & spot 75 sx plug in stub. - Tagged cement at 2420'
10-4-90 - Set 100 sx plug across salt zone from 1765' to 1150' & set 75 sx plug from 650' to 550' across 13-3/8" casing shoe.
10-5-90 - Plug did not hold. Spot 2nd 75 sx plug from 650' to 550' - tagged at 652'.
10-8-90 - Spot 10 sx plug at surface & installed dry-hole marker.

OVER

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Betty Gildon

TITLE

Regulatory Analyst

DATE

10/9/90

TYPE OR PRINT NAME

Betty Gildon

(915) 686-3714
TELEPHONE NO.

(This space for State Use)

APPROVED BY

R. A. Adkins

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

✓

CASING & TUBING RECORD AFTER PLUGGING

Csg Size	Wt. #/ft	Put in Well	Left in Well	Hole Size
20"	94#	61'	61'	-
13-3/8"	48#	608'	608'	17-1/2"
10-3/4"	55.5# & 60.7#	5,500'	3,127'	12-1/4"
7-5/8"	33.7, 26.4# & 29.7#	12,800'	4,966'	9-7/8"
5-1/2" Liner	23#	1,617'	1,617'	6-1/2"
3-1/2" Liner	10.3#	915'	915'	4-1/2"
2-7/8" Tubing		13,776'	0'	-