		HIGH A
DRILLIN		COMMENDATIONS
	ا الاستان المراجعة المراجع ليراقع الأراث المائية من المراجع المراجع المراجع المراجع المراجع المراجع المراجع ال المراجع المراجع	
	್ರಶ್ರೆ ಸಂಕರ್ಷವರು ಸಂಕರ್ಷಕರು ನಿರ್ದೇಶಕರು ನಿರ್ದೇಶಕರು ಕೊಂಡಿದೆ. ಕೊಂಡು ಸಂಕರ್ಷ ಕೊಂಡು ಸಂಕರ್ಷ ಸಂಕರ್ಷಕರು ಸಂಕರ್ಷಕರು ಸಂಕರ್ಷಕರು ಸಂಕರ್ಷಕರು ಸಂಕರ್ಷಕರು ಸಂಕರ್ಷಕರು ಸಂಕರ್ಷಕರು ಸಂಕರ್ಷಕರು ಸಂಕರ್ಣ	Date <u>May 7, 1979</u>

Company	THE SUPERIOR OIL COMPANY	Location Section	<u>18, T24S, R34E</u>
Well Name	#2 Government "L"	CountyLea	State <u>New Mexico</u>

## CASING PROGRAM

Set 20" at 50 Ft. (Rathole Machine)
Set 13-3/8" at 600 Ft.
Set 10-3/4" at 5500 Ft. (Delaware Lime)
Set 7-5/8" at 13,100 Ft. (Wolfcamp)
Set 5" Liner at 14,700 Ft. (Mississippi Lime)

RECOMMENDED DRILLING FLUIDS PROPERTIES

	Depth	Mud Weight	Viscosity	API Filtrate	pH	KCl %	Oil			
Ç	0 - 600'	8 5-9 6	34-42	NC	9.0					
0 - 600' 8.5-9.6 34-42 NC 9.0 Spud with a fresh water SUPER-COL® and Soda Ash spud mud. Paper-Ox and MIL-FIBER® for losses and unconsolidated formations.										
	600 - 5500	8.8-10.1	29-31	NC	10.0-11.0					
	Drill out with fresh water and drill redbeds. Convert to brine upon encountering Anhydrite to drill salt section to casing point. MIL-LIME® for pH; Paper-Ox and Cottonseed hulls for losses as required.									
	5500 - 13,100	9.0-9.5	28-30	NC	10.0-11.0					
	Drill out with cut brine 9.5 or less. Drill ahead, adding fresh water to control weight. Have weight below 9.1 prior to penetrating the Bone Spring. Use Paper-Ox and Cottonseed hulls or MIL-FIBER® for losses or seepage. Adjust fluid den- sity with brine 10 lb/gal as required in Wolfcamp. Mud up to run casing.									
	13,100-14,700	10.5-13.0	34-44	10-25	9.5-10.0					
	with a 10.5 lb	fresh wate:	r non-dispe ill ahead,	ersed Ben-E	x fluid wit	rstem. Displ h a density ty as requir	of			

MKT-DFR-2-10-76 9 REG. U.S. PAT. OFF.

RECEILED JUL - 9 1973 B O.C.D. HOBBS, OFFICE

.

.