

INCLINATION REPORT (One Copy Must Be Filled With Each Completion Report.)	
1. FIELD NAME Sioux Tansill	2. LEASE NAME Wilson 17 Federal
3. OPERATOR HNG Oil Company	
4. ADDRESS P.O. Box 2267, Midland, Texas 79702	
5. LOCATION (Section, Block, and Survey) Unit Letter P, 660' FSL & 660' FEL, Sec. 17, T26S, R36E	

[illegible]

17. Is any information shown on the reverse side of this form? ☐ yes ☒ no

18. Accumulative total displacement of well bore at total depth of 3700 feet = 175.60 feet.

19. Inclination measurements were made in - ☐ Tubing ☐ Casing ☐ Open hole ☒ Drill Pipe

20. Distance from surface location of well to the nearest lease line 660' feet.

21. Minimum distance to lease line as prescribed by field rules 330' feet.

22. Was the subject well at any time intentionally deviated from the vertical in any manner whatsoever? No

(If the answer to the above question is "yes", attach written explanation of the circumstances.)

Signature of Authorized Representative Richard B. Shaw
Name of Person and Title (type or print) Richard B. Shaw
Name of Company Price Drilling Company
Telephone: Area Code

Betty A. Gildon
Signature of Authorized Representative
Betty A. Gildon, Regulatory Clerk
Name of Person and Title (type or print)
HNG Oil Company
Operator
Telephone: 915 683-4871

My Commission Expires 2-4-81.

Subscribed and Sworn to before me on this 1 day of January 1980
Notary Public in and for Midland County, Texas

The Commission may require the submitta the original charts, graphs, or discs, resulting from the surveys.

copy to each appropriate completion for the well. (except Plugging Report)

This report shall be filed in the District Office of the Commission for the district in which the well is drilled, by attaching one

provisions of Statewide Rule 11.

An inclination survey made by persons or concerns approved by the Commission shall be filed on a form prescribed by the Commission for each well drilled or deepened with rotary tools or when, as a result of any operation, the course of the well is changed. No inclination survey is required on wells that are drilled and completed as dry holes that are plugged and abandoned. (Inclination surveys are required on re-entry of abandoned wells.) Inclination surveys must be made in accordance with the provisions of Subchapter B of this chapter.

- INSTRUCTIONS -

REMARKS:

☐ If additional space is needed, attach separate sheet and check here.

[illegible]

RECORD OF INCLINATION (Continued from reverse side)

DEC 19 1980

100