

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

N. M. OIL & GAS COMM. DIVISION
P. O. BOX 1859
SANTA FE, N.M. 87501

Form Approved.
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐
2. NAME OF OPERATOR
The Superior Oil Company
3. ADDRESS OF OPERATOR
P.O. Box 3901, Midland, Texas 79702
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1980' FNL, 1968' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐

☐
☐
☐
☐
☐
☐
☐
☐

(other) Operations to complete in Middle Morrow.

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12/18/82 Bled well, loaded tbg w/50 bbs BW, circ, bled well, POH, tally in
thru in hole, to 14,000', RV Dresser Titan, reverse circ, RD Dresser,
12/29/82 RU Jarrell WL, unable pull blanking plug, perf'd one 7/16" hole @
14,027', POH, bled well, POH, circ hole clean.
12/30/82 POH w/BHA, indications of loose junk around shoe, RIH w/pkr picker,
wash to 10,800'.
12/31/82 FIH w/BHA to 12,100', pushed junk to 13,100', hung BHA, jarred loose,
WIH from 13,100' to 13,640', (working junk down hole, stuck pkr
picker @ 13,640').
1/1/83 Jarred on pkr picker stuck @ 13,640', came loose, POH to 11,900'.
Well SI, WO orders.
1/2/83 WOO
1/3/83 WOO

Subsurface Safety Valve: Make and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED G. E. Tule TITLE Prod. Supt. DATE 1/26/83

Ge. F. Tule (This space for Federal or State)

(ORIG. SGD.) DAVID R. GLASS

APPROVED BY _____ DATE _____

CONDITIONS OF APPROVAL IF ANY

FEB 08 1983

MINERALS MANAGEMENT SERVICE
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side

RECEIVED

JAN 31 1983

OIL & GAS
MINERALS MGMT. SERVICE
ROSWELL, NEW MEXICO

Over

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well is conditioned for final inspection looking to approval of the abandonment.

GPO : 1981 O - 347-166

bled well, feed dry gas only, POH w/BHA & tbq, ran
6" magnet on ID 2,101, POH w/no recovery.
Fishing 8" magnet, POH, WIH, nec small pcs of meta
on magnet, PHW/new pkr picker & BHA, POH rec
add metal, GIN mill pkr to 14,037', POH, WO spea
Fished, flowed, tested, circ & cond hole, set
5 1/2" CIBP @ 12,440', capped w/35' cmt, CIBP @ 13,196'
W/35' cmt and @ 12,060' W/35' cmt on top.
WIH, ND BOP, NO tree, end of tbq @ 12,042' (tally)
displace 13.5# oil mud from hole w/10# BW, RD
& more out PU.
Clean location, move out frac tanks.
Suspend operations pending Bone Spring
evaluation. Will test Bone Spring.

1/4/83
1/5/83
1/8/83
1/10/83
1/16/83
1/17/83
1/18/83
1/19/83