STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

HO, OF COPICS RECEIVED	
NOITHBUTION	
MANTA FE	
ぎルえ	
U.S.G.5.	
LAND OFFICE	
08404708	

OIL CONSERVATION DIVISION &

DISTRIBUTION		P. O. BO	C2088	<i>h</i> D	Form C-103
SANTA FE	SANTA	SANTA FE, NEW MEXICO 87501			Revised 10-1-78
F1L Z			DEC 111	1981	5a. Indicate Type of Lease
LAND OFFICE	-				State Fee X
OPERATOR		• ,			5. State Oil & Gas Lease No.
			487 St [17	rik i	mmmmmm
SUNC	DRY NOTICES AND RE	EPORTS ON	WELLS	IR.	
USE "APPLIC	ENTION FOR PERMIT - " (FORM	C-101) FOR SUC	H PROPOSALS.)		7. Unit Agreement Name
OIL GAS WELL X	OTHER-		•		[']
2. Name of Operator					8. Farm or Lease Name
Coquina Oil Corporati	on			· .	Buckeye
3. Address of Operator	' 17				9. Well No.
P. O. Drawer 2960, Mi	dland, lexas /9/	02			10 Field and Deal on Wildow
4. Location of Well			3000		Lindes. Antelope Ridge
UNIT LETYERC	660 FEET FROM THE	North_	LINE AND	FEET FROM	
THE West LINE, SEC	15	2/10	2 <i>/</i> I⊏		
THE LINE, SEC	HWOY UIT	3HIP (4)	RANGE 341	NМРМ.	
	15. Elevation	(Show whether	DF, RT, GR, etc.)		12. County
	3516	' GL			Lea ())))))
Check	k Appropriate Box To	Indicate N	ature of Notice, Repo	ort or Oth	er Data
NOTICE OF	INTENTION TO:	1	sues	SEQUENT	REPORT OF:
		(<u>-</u>	•		
PERFORM REMEDIAL WORK	PLUG AND	ABANDON	REMEDIAL WORK		ALTERING CASING
TEMPORARILY ABANDON			COMMENCE DRILLING OPHS.		PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE P	LANS	OTHER		
OTHER					
	(6)	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
work) see Rule 1103.	Operations (Clearly state at	ii peninent aeid	nis, and give pertinent dates	i, including	estimated date of starting any proposed
Ran 309 jts 9-5/8" cas	ing as follows:		:		
200 i+c 47#/S 0	NE /I TC	10 EEO!	:		
309 jts 47#/S-9 Set @		12,550' 12,531'			
Set @		12,001			
Cmt'd w/900 sx Howco L	ite w/5#/sk KCl.	0.3% HR-5	. %#/sk Flocele	Tailed	w/600 sy Cl "H"
w/5# KC1, 0.5% Halad 2	22, 0.5% CFR-2. P	D @ 1:00	a.m. CST, 12/6/81	. WOC 1	8 hrs. Set slips.
cut off csg and instal	led wellhead. Ra	n temp su	rvey and found TO	C @ 7600)'. Test BOP's
and choke manifold to	7500 psi. o.k.	Test Hydr	il to 1800 psi, he	eld o.k.	Drill to float
collar, test casing to	3000 psi tor 30	min., o.k	. Drill to float	shoe.	Test to 3000 psi
for 30 min., o.k. Dri drilling ahead.	II snoe. Test To	rmation t	o 2500 psi, 12.8 j	ppg equi	valent, o.k. Now
or riving uneau.	'				
	•				
•					
18. I hereby certify that the informati	on above is true and comple	te to the best o	f my knowledge and belief.		
201	,				
SIGNED Bully M. Price	he	TITLE D	rilling Manager		December 8, 1981
4.20					Dr. 0 4 - 4001
Brig. State					Die a Mor
APPROVED BY		TITLE			DATE