STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

THE PROPERTY OF	LIMI	11415
we. of Corice Receives	\top	
DISTRIBUTION		
BANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPPRATOR	7	

UIL CONSERVATION DIVISION

DISTRIBUTION	Р. О. ВО	X 2088	Form C-103	
SANTA FE	SANTA FE, NEW MEXICO 87501		Revised 10-1-78	
FILE			5a. Indicate Type of Lease	
U.S.G.S.			State Fee Y	
OPERATOR			5, State Oil & Gas Lease No.	
	,			
SUNDR (DO NOT USE THIS FORM FOR PRO USE "APPLICATION")	Y NOTICES AND REPORTS ON POSALS TO DRILL OR TO DEEPEN OR PLUC BE TON FOR PERMIT - " (FORM C-101) FOR SU	WELLS ACK TO A DIFFERENT RESERVOIR. H PROPOSALS.)		
OIL XX GAS WELL WELL			7. Unit Agreement Name	
2. Name of Operator	OTHER-		8. Farm or Lease Name	
General Hydrocarbon 3. Address of Operator	Corp.		Maggie Lou Bigbee	
P. O. Box 88, Loving	ton, N. M. 88260		# 1 -3 1	
4. Location of Well 0 21	90 FEET FROM THE East	330	Pield and Pool, or Wildcat	
i	on 30 TOWNSHIP 25 S		CHILLIAN WAR	
THE DOG OIL LINE, SECTION			1PM.	
	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County Lea	
16. Check	Appropriate Box To Indicate N		Other Data	
	NTENTION TO:	-	ENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON X	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT	
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB		
		OTHER		
DTHER	LJ			
17. Describe Proposed or Completed Opwork) SEE RULE 1 (03.	perations (Clearly state all pertinent det	ails, and give pertinent dates, inclu	ding estimated date of starting any proposed	
8 5/8" Casing at 11	50 ' cement circulat	ed		
$5\frac{1}{2}$ " Casing at 36	64 ' cement circulat	ed		
1. Rig up pull prod	uction equirment			
2. Load hole with 1	.0 # Salt Gel			
3. Spot 100 ft. plu	ng across perfs. at 3	410 & Tag		
4. Shot 100 ft. plug at top of salt at 1450				
5. Surface plug and	marker			
18. I hereby certify that the information	above is true and complete to the best	of my knowledge and belief.		
BIGHED J. N. Guy	() () TITLE AS	zent	DATE 4-25	