UNITED STATES

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE WA-14160 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.) 1. oil gas well other 2. NAME OF OPERATOR Pogo Producing Company 3. ADDRESS OF OPERATOR P. 0. Box 10340, Midland, Texas 79702 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 1980' FSL & 1980' FWL AT TOP PROD. INTERVAL: 1980' FSL & 1980' FWL AT TOTAL DEPTH: 1980' FSL & 1980' FWL 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSÉQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other)	7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME Mosbacher 20 9. WELL NO. 1 10. FIELD OR WILDCAT NAME Bradley (C) 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 20, T-26-S, R-34-E 12. COUNTY OR PARISH Lea New Mexico 14. API NO. 15. ELEVATIONS (SHOW DF, KDB, AND WD) 3350' GR, 3377' KB (NOTE: Report results of multiple completion or zone change on Form 9-330.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinent Plug and abandon as described on attached pro is attached to procedure. Work is estimated to begin within three weeks	rectionally drilled, give subsurface locations and to this work.)* cedure. Diagrammatic well sketch

Subsurface Safety Valve: Manu. and Type	Set @	Ft.
18. I hereby certify that the foregoing is true and correct		
SIGNED Sofulliams TITLE Div. Operations	Мурате 10/27/86	
(This space for Federal or State office use	e) ('/	
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	DATE	