

Submit to Appropriate
District Office
State Lease - 4 copies
Fee Lease - 3 copies

State of New Mexico
Energy, Minerals and Natural Resources Department

Form O-102
Revised 1-1-89

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT I
P.O. Box 780, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL LOCATION AND ACREAGE DEDICATION PLAT

All Distances must be from the outer boundaries of the section

Operator Lewis B. Burleson, Inc.			Lease Stevens A-34		Well No 5
Unit Letter A	Section 34	Township 23S	Range 36E	NMPM	County Lea
Actual Footage Location of Well: 890 feet from the North line and 990 feet from the East line					
Ground level Elev. 3383.1	Producing Formation Yates-7R	Pool Jalmat (T-Y-7R)	Dedicated Acreage: 40 Acres		

1. Outline the acreage dedicated to the subject well by colored pencil or hatchure marks on the plat below.

2. If more than one lease is dedicated to the well, outline each and identify the ownership thereof (both as to working interest and royalty).


3. If more than one lease of different ownership is dedicated to the well, have the interest of all owners been consolidated by communitization, unitization, force-pooling, etc.?

☐ Yes ☐ No

If answer is "yes" type of consolidation

If answer is "no" list the owners and tract descriptions which have actually been consolidated. (Use reverse side of this form if necessary.)

No allowable will be assigned to the well until all interests have been consolidated (by communitization, unitization, forced-pooling, or otherwise) or until a non-standard unit, eliminating such interest, has been approved by the Division.



OPERATOR CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief.

Signature

Printed Name

Steven L. Burleson

Position

Vice-President

Company

Lewis B. Burleson, Inc.

Date

11-4-93

SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my knowledge and belief.

Date Surveyed

Signature & Seal of
Professional Surveyor

Certificate No.

0 330 660 990 1320 1650 1980 2310 2640 2000 1500 1000 500 0

COUNTY	LEA	FIELD	Undesignated	STATE	NM
OPR	CONOCO, INC.	API	30-025-27905	MAP	
NO	1	UNIT	East Hooper (Abo) Unit	CORD	
	Sec 34, T23S, R36E				
	890 FNL, 990 FEL of Sec				2-1-63 NM
	13 mi SW/Eunice	SPD	11-3-82	CMP	*12-14-82
		WELL CLASS: INIT	D	FIN	*D
		LSE. CODE			
	*13 3/8-1336-400 sx 1420x	FORMATION	DATUM	FORMATION	DATUM
	*8 5/8-3992-1300 sx 1414x				
		ID	9000 (ABO)	PRI	

*DRY & ABANDONED

CORR Verna #17 OPR ELEV *3387 GL, 3398 KB sub-s *10

F.R. 6-28-82
 PD 9000 RT (Abo)
 11-4-82 Drlg 490
 mw 9, vis 35
 11-11-82 Drlg "Tight"
 11-16-82 Drlg "Tight"
 *DST (Blinbry) 6986-7081, op 1 hr 31
 mins, rec 5490 FT SWTR -chl 110,000 ppm
 (Sampler rec 2450 CC SWTR), 1 hr 1 min
 ISIP 2945, FP 1041-2742, 2 hr 4 min FSIP
 2933
 *Cored (Abo) 8545-8602, rec 57 FT dolo
 12-6-82 TD 9000; "Tight"
 *2-14-83 TD 9000; Dry & Abandoned
 *LOG TOPS: Yates 3110, Seven Rivers 3325,
 Queen 3758, Grayburg 3990, San Andres 4520,
 Glorieta 5830, Blinbry 6234, Tubb 7110,
 Drinkard 7541, Abo 7885

2-1-63 NM

LEA
CONOCO, INC.

Undesignated
1 East Hooper (Abo) Unit
Sec 34, T23S, R36E

NM
Page #2

*2-14-83 Continued
*LOGS RUN: DI, SFL, BSL, GRL, CNL, FDC,
DIPM, CPL

*Denotes Changes & Additions

2-5-83 TEMPORARY COMPLETION ISSUED
2-19-83 RE-ISSUE OF SUSPENDED COMPLETION

2-1-63 NM
IC 30-025-70522-82

COUNTY LEA FIELD Undesignated STATE NM
 OPR. COMOCO, INC. APL. 30-025-27905
 NO 1 LEASE East Hooper (Abo) Unit MAP
Sec 34, T23S, R36E CO-ORD
890 FNL, 990 FEL of Sec 2-1-63 NM
13 mi SW/Eunice SPD 11-3-82 CML 1-31-83

CSC

Csg (NR)

WELL CLASS: INIT D FINSUS LSE. CODE			
FORMATION	DATUM	FORMATION	DATUM
ID 9000 (Abo)		PRD	

SUSPENDED OPERATIONS

CONTR Verna 17 OPRN ELEV 3383 GL sub-s 11

11-4-82 F.R. 6-28-82
 Drlg 490
 mw 9, vis 35
 11-11-82 Drlg "Tight"
 11-16-82 Drlg "Tight"
 12-6-82 TD 9000; "Tight"
 1-31-83 TD 9000; Suspended Operations
 2-5-83 TEMPORARY COMPLETION ISSUED

2-1-63 NM
 IC 30-025-70522-82