

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐

2. NAME OF OPERATOR
TEXACO Inc.

3. ADDRESS OF OPERATOR
P. O. Box 728, Hobbs, New Mexico 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 660' FNL & 1980' FEL

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

Plug Back and Recomplete ☒

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. RIGGED UP. PULL RODS AND PUMP. INSTALL BOP. PULL TUBING.
2. SET CEMENT RETAINER @ 3273'. CEMENTED BELOW RETAINER W/200 SX CLASS H CEMENT CONTAINING .5% HALAD-9 INTO FORMATION. SQUEEZED W/ ADDL 100 SX CLASS H CEMENT CONTAINING 2% CACL. PBTD 3273'.
3. PERFORATE 5 1/2" CSG W/2-JSPF FROM 3204-3210' AND @ 3214, 18, 34, 37, & 3240'.

Subsurface Safety Valve: Manu. and Type _____

Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Asst Dist Mgr

DATE

8-30-84

ACCEPTED FOR RECORD (This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL IF ANY:

SEP 6 1984

Carlsbad, NEW MEXICO

*See Instructions on Reverse Side

5. LEASE

16-030177 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

C. W. Shepherd Federal (b) *Federal*

9. WELL NO.

10. FIELD OR WILDCAT NAME

Undesignated

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec 5, T-26-S, R-37-E

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
2977' (GR)

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

M. L. L. L. L.

RECEIVED

SEP 12 1984

G.C.D.
HOBBS OFFICE

4. SET PKR @ 3128'. ACIDIZE PERFS 3204-3240' W/5000 GALS 15% NEFE ACID DROPPING BALL SEALERS THROUGHOUT TREATMENT.
5. SET CIBP @ 3150' AND SPOT 40' CEMENT ON PLUG.
6. PERFORATE 5 1/2" CASING W/2-JSPF FROM 3013-3018'.
7. SET PKR @ 2974'. ACIDIZE PERFS 3013-3018' W/1000 GALS 15% NEFE ACID DROPPING BALL SEALERS THROUGHOUT TREATMENT.
8. SET CIBP @ 3008' AND SPOT 35' CEMENT ON PLUG. PERFORATE 5 1/2" CASING W/2-JSPF FROM 2951'-2958' AND @ 2964', 66', 67', & 2968'.
9. SET PKR @ 2850'. ACIDIZE PERFS 2951'-2968' W/1000 GALS 15% NEFE ACID DROPPING BALL SEALERS THROUGHOUT TREATMENT.
10. SET CIBP @ 2900' AND SPOT 40' CEMENT ON TOP OF PLUG. PBTD 2860'.
11. WELL DID NOT PRODUCE. COMPLETE REMEDIAL WORK AS SHUT-IN, UNECONOMICAL TO PRODUCE, 8-28-84.

RECEIVED

SEP 12 1984

O.C.D.
HOBBES OFFICE