


UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY



ROSWELL, N.M.

NOT COPY

Form Approved.
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☐
well well

2. NAME OF OPERATOR
Jubilee Energy Corporation

3. ADDRESS OF OPERATOR 79705
3100 N. "A", Bldg. E, #103, Midland, TX

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1980' FNL & 500' FEL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☒
(other) ☐

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☒

5. LEASE
NM-29694
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Exxon "B" Federal

9. WELL NO.
1

10. FIELD OR WILDCAT NAME
Double "X" Delaware

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 21, T-24-S, R-32-E

12. COUNTY OR PARISH
Lea

13. STATE
NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3586' GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

All P&A operations were performed in accordance with BLM instructions and witnessed by BLM representative.

1. Load hole with 9.5# mud.
2. Run and set wireline bridge plug @ 4750'. Spot 35' of cement from 4750' to 4715'.
3. Cut 5½" casing @ 4122'. Pull casing.
4. Run 2 7/8" tubing to 4122' and spot 35 sx. cement from 4122' to 4020'. WOC 12 hrs. and tag plug. Okay.
5. Spot 30 sx. cement from 1300' to 1200' (salt section). WOC 4 hrs. and check top of cement. Okay.
6. Spot 50 sx. plug from 1100' to 970'. (8 5/8" 24# @ 980')

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct


SIGNED _____ TITLE President DATE 7-25-83

APPROVED BY _____ (This space for Federal or State office use)
CONDITIONS OF APPROVAL, IF ANY: _____ TITLE CARLOSAD DATE 3-15-85

RECEIVED

MAR 16 1995

U.S. DEPT. OF JUSTICE
FEDERAL BUREAU OF INVESTIGATION

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other ☐
2. NAME OF OPERATOR
Jubilee Energy Corporation
3. ADDRESS OF OPERATOR 79705
3100 N. "A", Bldg. E, #103, Midland, TX
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1980' FNL & 500' FEL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☒

(other) ☐

SUBSEQUENT REPORT OF:

☐

☐

☐

☐

☐

☐

☐

☐

5. LEASE
NM-29694
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
- UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Exxon "B" Federal
9. WELL NO.
1
10. FIELD OR WILDCAT NAME
Double "X" Delaware
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 21, T-24-S, R-32-E
12. COUNTY OR PARISH
Lea
13. STATE
NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3586' GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Continued from previous page.

7. Spot 10 sx. cement in top of 8 5/8" casing @ surface. Install dry hole marker. Clean and level location. Well P&A on 7-7-83.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE President DATE 7-25-83

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: