

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPI
(Other instructions
verse 1'de)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER P&A		5. LEASE DESIGNATION AND SERIAL NO. NM-28181
2. NAME OF OPERATOR TEX/CON Oil & Gas Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME NA
3. ADDRESS OF OPERATOR 9401 Southwest Freeway, Houston, TX 77074		7. UNIT AGREEMENT NAME N.E. Salado Draw (Deep)
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit Letter E, 1980' FNL & 660' FWL		8. FARM OR LEASE NAME N.E. Salado Draw (Deep)
14. PERMIT NO.		9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3319.8' GR		10. FIELD AND POOL, OR WILDCAT Salado Draw Wolfcamp
		11. SEC., T., R., N. OR BLK. AND SURVEY OR ARMA Sec. 6-T26S-R34E
		12. COUNTY OR PARISH Lea
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	
(Other) <input type="checkbox"/>			

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

11-1-90. RIH w/CIBP & set @ 12950'. Dumped 50' of cmt on top of CIBP. RIH & cut 7" csg - pulled & layed down 257 jts. of csg. RIH w/tbg workstring & reversed out. Spot 30 sx cmt plug from 9800'-9900'. Spot 30 sx cmt plug from 6800'-6900'. Spot 30 sx cmt plug @ 5350'. Tagged top of cmt plug @ 5120'. Shot 9-5/8" csg & cut @ 2000'. Pumped 60 sx cmt plug & displaced. Tagged top of cmt plug @ 1890'. RIH to 850' & pumped 60 sx cmt plug & displaced. POOH to 30' & pumped 20 sx surface plug. Welded on steel cap & installed dry hole marker. Used 9.5 ppg mud-laden fluid between plugs as requested. P&A completed on 12-29-90. Location & pit were levelled & backfilled. Notified Mr. Jack Johnson with BLM prior to plugging & had approval from Mr. Shannon Shaw for the CIBP.

0+3: BLM, Carlsbad Resource Area
Carlsbad, NM
1: NM OCD, Hobbs, NM
1: H. Dupuy, L. Hambek,
J. Hresko, File

Approved as to plugging of the well bore.
Liability under bond is released until
surface restoration is completed.

RECEIVED
OCT 7 9 02 AM '91
CARLSBAD RESOURCE AREA

18. I hereby certify that the foregoing is true and correct
SIGNED [Signature] TITLE Supervisor, Environmental & Regulatory Affairs DATE 10/3/91
(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE 10/22/91
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

RECEIVED

OCT 24 1991

068
HOBBS OFFICE